

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUN 25 2013

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

JMN 1318429370

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: Chevron USA	4323	Contact: Amy Barnhill
Address: 2401 Avenue O Eunice, NM 88231		Telephone No.: 432-940-8524
Facility Name: Bogle Flats #18		Facility Type: Tank Battery

Surface Owner: State of NM	Mineral Owner: State of NM	API No. 30-015-28884
----------------------------	----------------------------	----------------------

LOCATION OF RELEASE

Unit Letter G-SW/4 of NE/4	Section 16	Township 22S	Range 23E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
----------------------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 322339.40 Longitude 1043609.76

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 22 Bbls	Volume Recovered: 20 Bbls
Source of Release	Date and Hour of Occurrence: 6-10-2013 - 12:00pm	Date and Hour of Discovery 6-10-2013 - 7pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher (575) 748-1283 x 108	
By Whom? Amy Barnhill	Date and Hour: 6-11-2013 - 8:42am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

There was a leak under a tank. The additional weight of the fluid evidently forced open a bad spot and we lost the fluid in the berm.

Describe Area Affected and Cleanup Action Taken.*

Spill inside the berm. Nabors trucking picked up 20 Bbls of fluid. Gator PW/Oil absorbent was spread over affected area.

Further remediation will be performed in accordance with a NMOCD approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Amy Barnhill		OIL CONSERVATION DIVISION	
Printed Name: Amy Barnhill		Approved by Environmental Specialist: Signed By <i>Mike Bratcher</i>	
Title: HE Specialist		JUL 03 2013	Expiration Date:
E-mail Address: ABarnhill@chevron.com		Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: August 3rd 2013	
Date: 6-21-2013 Phone: 432-940-8524		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-1701