OCD Artesia

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED
OMB NO. 1004-0135
 Expires: July 31, 2010

SUNDRY Do not use the abandoned we SUBMIT IN TRI 1. Type of Well Oil Well Gas Well Otl 2. Name of Operator COG OPERATING LLC 3a. Address ONE CONCHO CENTER 600 MIDLAND, TX 79701	7. If U NN 8. Wel Mu 9. AP Mu 10. Fi BU	5. Lease Serial No. MultipleSee Attached 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. NMNM88525X 8. Well Name and No. MultipleSee Attached 9. API Well No. MultipleSee Attached 10. Field and Pool, or Exploratory BURCH KEELY-GLORIETA-UPPER YE GRAYBURG JACKSON SR-Q-GRBG-S				
Location of Well (Footage, Sec., T MultipleSee Attached	11. Co	11. County or Parish, and State EDDY COUNTY, NM EPORT, OR OTHER DATA				
TYPE OF SUBMISSION	COPRIATE BOX(ES) TO	J INDICATE		NOTICE, REPORT 	, OR OTHE	K DATA
☑ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	□ Nev	cture Treat v Construction g and Abandon	Production (State Production Reclamation Recomplete Temporarily Alt Water Disposal	oandon	☐ Water Shut-Off ☐ Well Integrity ☑ Other Venting and/or Flari
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the won following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fit COG Operating LLC, respectf 18-T17S-R30E Number of wells to flare: (16) Burch Keely Unit 564 30-015-Burch Keely Unit 572 30-015-Burch Keely Unit 570 30-015-Burch Keely Unit 573 30-015-Burch Keely Unit 573 30-015-Burch Keely Unit 884 30-015-Burch Keely Unit 854 30-015-Burch Keely Unit 855 30-015-Burch Keely Unit 555 30-015-Burch Keely Unit 555 30-015-Burch Keely Unit 555 30-015-Burch Keely Unit 573 30-015-Burch Keely Unit 555 30-015-Burch Keely Unit 555 30-015-Burch Keely Unit 555 30-015-Burch Keely Unit 555 30-015-	ally or recomplete horizontally, k will be performed or provide operations. If the operation resonderment Notices shall be fill inal inspection.) ully request to flare at the same of th	give subsurface the Bond No. o sults in a multip ed only after all Burch Keely	locations and meast n file with BLM/BIA le completion or record unit 18A Batter La	ared and true vertical de A. Required subsequent ompletion in a new inter ling reclamation, have by. UL H-Sec	pths of all pertii reports shall be eval, a Form 316 een completed. REC JUN NMOC SEE ATT	nent markers and zones. filed within 30 days 50-4 shall be filed once
	#Electronic Submission # For COG O nmitted to AFMSS for proc	PERATING LI	LC. sent to the C	arlsbad 05/08/2013 (13KMS5		
Signature (Electronic S	Date 05/03/2	013				
Approved By JERRY BLAKLEY Conditions of approval, if any, are attached ertify that the applicant holds legal or each which would entitle the applicant to conductive 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent section 1001.	itable tide to those rights in the ct operations thereon. U.S.C. Section 1212, make it a	not way ant or subject lease	TitleLEAD PET Office Carlsba	AP JUI	PROVE	Date 05/08/2013
States any raise, nerritous of Haddulent S	tatements of representations as	to any matter w	ioni na junisticiion.	CARLS	SBAD FIELD C	OFFICE

Additional data for EC transaction #206112 that would not fit on the form

5. Lease Serial No., continued

NMLC028784A NMLC028784B NMLC028793A NMLC028793C

Wells/Facilities, continued

Agreement	Lease	Well/Fac Name, Number	API Number	Location
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 564	30-015-39869-00-S1	Sec 18 T17S R30E Lot 2 1713FNL 355FWL
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 411	30-015-36263-00-S1	Sec 18 T17S R30E Lot 2 1910FNL 990FWL
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 548	30-015-39442-00-\$1	Sec 18 T17S R29E Lot 1 440FNL 460FWL
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 549	30-015-39522-00-S1	Sec 18 T17S R30E Lot 1 330FNL 1000FWL
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 550	30-015-39523-00-S1	Sec 18 T17S R30E NENW 330FNL 1650FWL
NMNM88525X	NMLC028793C	BURCH KEELY UNIT 552	30-015-39443-00-S1	Sec 18 T17S R30E NENW 1120FNL 2480FWL
NMNM88525X	NMLC028793C	BURCH KEELY UNIT 555	30-015-39566-00-S1	Sec 18 T17S R30E NENE 330FNL 330FEL
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 556	30-015-39907-00-S1	Sec 18 T17S R30E Lot 1 1004FNL 457FWL
NMNM88525X	NMLC028793C	BURCH KEELY UNIT 561	30-015-39318-00-S1	Sec 18 T17S R30E NWNE 990FNL 1650FEL
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 566	30-015-39870-00-S1	Sec 18 T17S R30E SENW 1650FNL 1650FWL
NMNM88525X	NMLC028793C	BURCH KEELY UNIT 570	30-015-40267-00-S1	Sec 18 T17S R30E NESE 2310FSL 990FEL
NMNM88525X	NMLC028784B	BURCH KEELY UNIT 572	30-015-40268-00-S1	Sec 18 T17S R30E SENW 2492FNL 2257FWL
NMNM88525X	NMLC028793C	BURCH KEELY UNIT 573	30-015-40269-00-S1	Sec 18 T17S R30E SWNE 2120FNL 2310FEL
NMNM88525X	NMLC028793A	BURCH KEELY UNIT 582	30-015-40272-00-S1	Sec 18 T17S R30E SWSE 1310FSL 2025FEL
NMNM88525X	NMLC028784A	BURCH KEELY UNIT 854	30-015-40378-00-X1	Sec 24 T17S R29E SWNW 1620FNL 1260FWL
NMNM88525X	NMLC028793C	BURCH KEELY UNIT 939H	30-015-39573-00-S1	Sec 18 T17S R30E Lot 1 1152FNL 497FWL

32. Additional remarks, continued

Burch Keely Unit 566 30-015-39870 Burch Keely Unit 556 30-015-39907 Burch Keely Unit 549 30-015-39522 Burch Keely Unit 550 30-015-39523 Burch Keely Unit 552 30-015-39443 Burch Keely Unit 561 30-015-39318 Burch Keely Unit 411 30-015-36263

500 Oil 1213 MCF Requesting to flare from 5/6/13 - 6/6/13 Due to DCP shut in. Schematic attached.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

6/8/2013

Condition of Approval to Flare Gas

- 1. Report all volumes on OGOR reports.
- 2. Comply with NTL-4A requirements
- 3. Subject to like approval from NMOCD
- 4. Flared volumes will still require payment of royalties
- 5. Install gas meter on vent/flare line to measure gas prior to venting/flaring operations if it is not equipped as such at this time. Gas meter to meet all requirements for sale meter as Federal Regulations and Onshore Order #5.
- 6. This approval does not authorize any additional surface disturbance.
- 7. Submit updated facility diagram as per Onshore Order #3.
- 8. Approval not to exceed 90 days for date of approval.
- 9. Submit Subsequent Report with actual volumes of gas flared for each month gas is flared.
- 10. If flaring is still required past 90 days submit new request for approval.
- 11. If a portable unit is used to flare gas it must be monitored at all times.
- 12. Comply with any restrictions or regulations when on State or Fee surface.

JDB682013