


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Burch Kelly Unit #205	Facility Type	Injection Line
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-015-03133

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	26	17S	29E					Eddy

Latitude 32.80008 Longitude 104.04331

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 10bbls	Volume Recovered 8bbls
Source of Release Injection line	Date and Hour of Occurrence 08-01-2013	Date and Hour of Discovery 08-01-2013 11:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A ditcher hit a buried fiberglass injection line. The line has been repaired and back in service.		
Describe Area Affected and Cleanup Action Taken.* Initially 10bbls of produced water were released from a fiberglass injection line that was struck by a ditcher. We were able to recover 8bbls of produced water with a vacuum truck. All free fluids have been removed. A work plan will be presented to the NMOCD/BLM for approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Robert Grubbs Jr.</i>		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor Signed By <i>M. L. Berman</i>	
Title: Senior Environmental Coordinator		Approval Date: AUG 16 2013	Expiration Date:
E-mail Address: rgrubbs@concho.com		Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: 8-13-2013 Phone: 432-661-6601			

\* Attach Additional Sheets If Necessary

September 16, 2013 2RP-1834