

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

AUG 15 2013

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NJM 1322834078

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Burch Keely Unit #205	Facility Type	Pasture

Surface Owner	Federal	Mineral Owner		Lease No. (API#)	30-015-03133
---------------	---------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	26	17S	29E					Eddy

Latitude 32 48.163 Longitude 104 02.567

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	75bbbls	Volume Recovered	50bbbls
Source of Release	Fiberglass line	Date and Hour of Occurrence	08-14-2013	Date and Hour of Discovery	08-14-2013 11:00am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	08-15-2013 10:03am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A fiberglass fitting came loose. Replaced the fitting a new fitting.

Describe Area Affected and Cleanup Action Taken.*

Initially 75bbbls of produced water were released due to a fitting came loose on a fiberglass line. We were able to recover 50bbbls with a vacuum truck. All free fluid has been recovered. The spill was located in the pasture. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOCD/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Robert Grubbs Jr.*

Printed Name: Robert Grubbs Jr.

Title: Senior Environmental Coordinator

E-mail Address: rgrubbs@concho.com

Date: 08-15-2013

Phone: 432-661-6601

Approved by District Supervisor

Signed By

Mike Bratcher

Approval Date:

AUG 16 2013

Expiration Date:

Conditions of Approval:

Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION

Attached ☐

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

Sept. 16, 2013

2RP-1835