


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

NJMW 1322938466

Name of Company		COG OPERATING LLC 229/37	Contact	Pat Ellis
Address		600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name		RJ Unit #125	Facility Type	Tank Battery
Surface Owner		Federal	Mineral Owner	
			Lease No. (API#)	30-015-03783

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	35	17S	29E					Eddy

Latitude 32.79474 Longitude 104.04760

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	35bbls	Volume Recovered	32bbls
Source of Release	Discharge water line	Date and Hour of Occurrence	08-09-2013	Date and Hour of Discovery	08-09-2013 11:00am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	08-12-2013 1:38pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Valve washed out on the discharge line. Removed discharge line going to the remover pump.

Describe Area Affected and Cleanup Action Taken.*

Initially 35bbls of produced water were released from a discharge water line we were able to recover 32bbls with a vacuum truck. All free fluid has been recovered. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor: Signed By 	
Title: Senior Environmental Coordinator		Approval Date: AUG 16 2013	Expiration Date:
E-mail Address: rgrubbs@concho.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08-13-2013 Phone: 432-661-6601		Remediation per OCD Rule & Guidelines, & like approval by BLM, SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

September 16, 2013

2RP-1837