

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NJMW1322455789

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Dakota Resources <i>5691</i>	Contact LaWayne Day
Address 4914 N. Midkiff Midland TX. 79705	Telephone No. 432-697-3420
Facility Name Federal Trigg #1	Facility Type SWD

Surface Owner BLM	Mineral Owner BLM	API No. 3001525006
--------------------------	--------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter L	Section 7	Township 215	Range 28E	Feet from the 1980	North/South Line South	Feet from the 660	East/West Line West	County Eddy
-------------------------	---------------------	------------------------	---------------------	------------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 40	Volume Recovered 0
Source of Release Hole in water tank	Date and Hour of Occurrence	Date and Hour of Discovery 8/6/13 9a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM OCD to Randy Day 8/8/2013	
By Whom? J.D.Machacek	Date and Hour 8/6/2013 (11:00 a.m.)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Had hole in 500 bbl. tank that we pumped out of to injection well. Water and some skim oil leaked out into burm to front side of tank some leaking out at low spot at gate area on to location pad.

Describe Area Affected and Cleanup Action Taken.*

Everything was soaked in dirt by morning. Will get backhoe and crew to pick up A.S.A.P.



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>LaWayne Day</i>		OIL CONSERVATION DIVISION	
Printed Name: LaWayne Day		Approved by Environmental Specialist <i>M. H. [Signature]</i>	
Title: Production Foreman		Approval Date: AUG 12 2013	Expiration Date:
E-mail Address: lawayned@dakotares.com		Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	
Date: 08/08/2013 Phone: 432-413-3185		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
September 12, 2013

2RP-1814