

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED	Form C-141
AUG 06 2013	Revised August 8, 2011
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.	

Release Notification and Corrective Action

JMW 1321937220		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Oxy Permian Ltd. 16696		Contact Chancey Summers			
Address 1017 W. Stanolind Rd, Hobbs, NM 88240		Telephone No. (575) 397-8216			
Facility Name Cypress 34 Federal #6H		Facility Type Well location			
Surface Owner BLM		Mineral Owner		API No. 30-015-38366	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	34	23S	29E	400	South	400	West	Eddy

Latitude N 32.25503° Longitude W 103.97884°

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10 bbls	Volume Recovered 0 bbls
Source of Release Over pressure on flow line	Date and Hour of Occurrence 07/15/2013	Date and Hour of Discovery 07/15/2013
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-NMOCD; Jennifer Van Curen, James Amos- BLM	
By Whom? Chancey Summers	Date and Hour 07/16/2013 @ 11:15 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Over pressure on a flow line caused 10 bbls of water to leak onto the ground. No fluids were recovered.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 275' x 50'. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chancey Summers	Approved by Environmental Specialist: Signed By 	
Title: HES Specialist	AUG 07 2013	Expiration Date:
E-mail Address: Chancey.Summers@oxy.com	Approval Date:	
Date: 8-6-13 Phone: (575) 397-8216	Conditions of Approval: Remediation per OCD Rule & Guidelines, & attached <input type="checkbox"/> like approval by BLM. SUBMIT REMEDIATION	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
September 7, 2013

2RP-1798