


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NTM 1322828129 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Arabian 6 Fee #001	Facility Type	Tank Battery
Surface Owner	Private	Mineral Owner	
		Lease No. (API#)	30-015-39405

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	06	19S	26E					Eddy

Latitude 32.68414

Longitude 104.42859

NATURE OF RELEASE

Type of Release	100bbls of produced water	Volume of Release	100bbls	Volume Recovered	90bbls
Source of Release	Water tank	Date and Hour of Occurrence	07-31-2013	Date and Hour of Discovery	07-31-2013 3:30pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOC D / Jim Amos - BLM		
By Whom?	Michelle Mullins	Date and Hour	08-01-2013 07:44am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Lightning struck the spare water tank. Replaced water tank.

Describe Area Affected and Cleanup Action Taken.*

Initially 100bbls of produced water were released due to a lightning strike on one of our fiberglass tanks. We were able to recover 90bbls of produced water. The entire release was contained inside the lined facility. All free fluids have been recovered. Any contaminated gravel has been removed, the liner has been washed, and we have replaced with clean gravel as necessary. This facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor:	Signed By <i>Mike Bratcher</i>
Title: Senior Environmental Coordinator		Approval Date: AUG 13 2013	Expiration Date:
E-mail Address: rgrubbs@concho.com		Conditions of Approval:	
Date: 08-13-2013 Phone: 432-661-6601		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Remediation per OCD Rule &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:

2RP-1833
September 16, 2013