

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report		
Name of Company <u>Devon Energy</u> <u>6137</u>	Contact <u>Tracy Kidd, Foreman</u>	
Address <u>6488 Seven Rivers Hwy, Artesia, NM 88210</u>	Telephone No. <u>575-513-0628</u>	
Facility Name <u>Cotton Draw Unit 159H</u>	Facility Type <u>Oil Well</u>	
Surface Owner	Mineral Owner	API No. <u>30-015-40385</u>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	13	25S	31E	330	South	660	West	Eddy

Latitude 32.1239320901639 Longitude 103.738011560144

NATURE OF RELEASE

Type of Release <u>Spill</u>	Volume of Release <u>100bbls</u>	Volume Recovered <u>100bbls</u>
Source of Release <u>Bent load line</u>	Date and Hour of Occurrence <u>07/24/2013, 10:00 AM</u>	Date and Hour of Discovery <u>07/24/2013, 10:00 AM</u>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>Mike Bratcher/ OCD & Jim Amos/BLM</u>	
By Whom? <u>Aaron Kidd, Assistant Foreman</u>	Date and Hour <u>07/24/2013 OCD 10:30 AM & BLM 10:45 AM</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
At the Cotton Draw 159, a water truck backed into a load line causing a 100 barrel spill of produce water.

Describe Area Affected and Cleanup Action Taken.*
NO SIF POTENTIAL - CLASS II INCIDENT - At the Cotton Draw 159, a water truck backed into a load line causing a 100 barrel spill. A water transporter was backing up to the load line and hit the line. When he hit the load line it broke the fiber glass water tank resulting in a produced water spill that was kept within the lined containment. Shut in well recovered all 100 barrels of water and repaired tank.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION	
Signature: <u>Graciela C. Bustamante</u>	Approved by Environmental Specialist: <u>Signed By Mike Bratcher</u>
Printed Name: <u>Graciela C. Bustamante</u>	Approval Date: <u>JUL 31 2013</u> Expiration Date:
Title: <u>Field Admin Support</u>	Conditions of Approval: <u>Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION</u>
E-mail Address: <u>gracie.bustamante@dvn.com</u>	Attached <input type="checkbox"/>
Date: <u>07/29/2013</u> Phone: <u>575-746-5561</u>	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
August 31, 2013 2RP-1781