

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1321848019

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company-Cimarex Energy <i>215099</i>		Contact- James Tinney	
Address-600 N Marienfeld Ste 600, Midland Tx 79701		Telephone No. 575 706 0095	
Facility Name-VERMAJO SWD#1		Facility Type- DISPOSAL FLOW LINE	
Surface Owner <i>FED</i>		Mineral Owner	
		Lease No. <i>30-013-40644</i>	

LOCATION OF RELEASE


Unit Letter <i>O</i>	Section 15	Township 17 S	Range 28 E	Feet from the 900	North/South Line south	Feet from the 2530	East/West Line east	County - Eddy
-------------------------	---------------	------------------	---------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude- 32.829636 Longitude- -104.163492

NATURE OF RELEASE

Type of Release- PW	Volume of Release-40 bbls	Volume Recovered-0 bbls
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Release Date <i>7/27/13</i> Confirmed <i>8/6/13</i> If YES, To Whom? JIM AMOS(BLM) MIKE BRATCHER(OCD) <i>via phone call</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Take

Pumper was leaving Vermejo SWD 1 when he found a leak in the poly line coming from the Pere Marquette 18 battery. He went to Pere Marquette 18 batt And made sure pump was off. Called out crew to repair poly line.

Describe Area Affected and Cleanup Action Take

40' x 1' wide area to the south of the ROW and 100yard x 2-3' wide along ROW. Water ran off and was nothing to pick up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>James Tinney</i>		OIL CONSERVATION DIVISION	
Printed Name: James Tinney		Approved by District Supervisor:- Signed By <i>Mike Bratcher</i>	
Title: Assistant Production Foreman		Approval Date: AUG 06 2013	Expiration Date:
E-mail Address: jtinney@cimarex.com		Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: 7/31/13 Phone: 575-706-0095		PROPOSAL NO LATER THAN: <i>September 06, 2013</i>	

* Attach Additional Sheets If Necessary

2RP-1789