


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating 269324	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: West B # 45	Facility Type: Oil Producer

Surface Owner: Federal	Mineral Owner:	API No.: 3001526099
------------------------	----------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	09	17S	31E	660	South	1980	West	Eddy

Latitude: 32.84369 Longitude: -103.87608

NATURE OF RELEASE



Type of Release: Produced Water	Volume of Release: 5gal	Volume Recovered: 0
Source of Release: Poly Pipeline	Date and Hour of Occurrence: 08/18/2013 10:30am	Date and Hour of Discovery: 08/18/2013 10:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton- BLM	
By Whom? Brian Wall	Date and Hour 08/19/2013 2:00pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: A Small pin hole in flowline developed resulting in spraying water mist. I Shut in well head to stop the spraying. Possible line fatigue.

Describe Area Affected and Cleanup Action Taken.*: 15' x 10' area

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by District Supervisor Signed By 	
Title: Construction Foreman II	Approval Date: AUG 26 2013	Expiration Date:
E-mail Address: bwall@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08/20/2013 Phone: 806-367-0645	Remediation per OCD Rule & Guidelines, &	

* Attach Additional Sheets If Necessary

like approval by BLM. **SUBMIT REMEDIATION**
PROPOSAL NO LATER THAN:

September 26, 2013

2RP-1862