

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

AUG 26 2013

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

nJMW 1323953381

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Apache Corporation	Contact	Larry Bruce Baker
Address	PO Box 1849, Eunice, NM 88231	Telephone No.	(432) 631-6982
Facility Name	Red Lake 29-1 State #1	Facility Type	Production Heater

Surface Owner	State	Mineral Owner		API No.	3001533579
---------------	-------	---------------	--	---------	------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	29	17S	28E	1636	FSL	995	FEL	Eddy

Latitude 32.802522 N Longitude 104.192650 W

#### NATURE OF RELEASE

Type of Release	Oil	Volume of Release	22 bbls	Volume Recovered	20 bbls
Source of Release	Production Heater	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	6/11/13 1240 hrs
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The gasket on the production heater fire tube failed releasing 22 bbls of oil. The power was turned off to the wellheads and a vacuum truck was called. The vacuum truck recovered 20 bbls of oil. The fire tube was pulled to replace the gasket.

Describe Area Affected and Cleanup Action Taken.\*

A total of 7,113 sq ft of pad and pasture was affected. The site will be delineated for further action.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Larry Bruce Baker</u>	OIL CONSERVATION DIVISION	
Printed Name: Larry Bruce Baker	Approved by Environmental Specialist:	Signed By: <u>Mike Beaudin</u>
Title: Environmental Tech	AUG 27 2013	Approval Date:
E-mail Address: larry.baker@apachecorp.com	Expiration Date:	
Date: <u>8-26-13</u>	Phone: (432) 631-6982	Conditions of Approval:
Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:		Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

September 27 2013

2RP-1875