


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

**Release Notification and Corrective Action**

*nJMW 1325536299* OPERATOR  Initial Report  Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Big Eddy Unit 33 Tank Battery	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-20369	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	4	20S	31E					

Latitude N 32.596782 Longitude W 103.86772

**NATURE OF RELEASE**

Type of Release: Produced water	Volume of Release: 80 Bbls	Volume Recovered: 60 Bbls
Source of Release: 4" truck load line	Date and Hour of Occurrence: 8/21/13, Time unknown	Date and Hour of Discovery: 8/21/13 Time 11:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104	
By Whom? Tony Savoie	Date and Hour 8/21/13 at 5:40 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The truck loaded developed a leak due to internal corrosion, the tank valve was shut and the load line was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The spill stayed inside the earthen containment around the tank location, the bermed area measured approximately 30 ft. by 55 ft. Approximately 1650 sq. ft. of containment area was impacted by the release. All of the free product was removed at the time of discovery. A remediation plan will be submitted to the NMOCD. The remediation will comply with the NMOCD and BLM guidelines for spill remediation

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist:	Signed By: <i>Mike Beaman</i>
Title: Waste Management and Remediation Specialist	Approval Date: <b>SEP 11 2013</b>	Expiration Date:
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION</b>	Attached <input type="checkbox"/>
Date: 9/10/13	Phone: 432-556-8730	

\* Attach Additional Sheets If Necessary

**PROPOSAL NO LATER THAN:**  
*October 11, 2013*

*2RP-1905*