


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

Submit Copy to Appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*njmw* 1326329033

**OPERATOR**

Initial Report  Final Report

Name of Company	Pyote Well Service LLC <i>29/8/13</i>	Contact	Jerry Burton
Address	400 W Illinois Ave STE 950	Telephone No.	432-448-4917
Facility Name	Rhomer #1 SWD BATTERY	Facility Type	Disposal
Surface Owner	FEE	Mineral Owner	FEE
		API No.	30-015-25722

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	23	22S	27e	1980 N	N	1980 W	W	EDDY

Latitude 32.3799890160328 Longitude 104.162618544465

**NATURE OF RELEASE**

Type of Release	PRODUCE WATER	Volume of Release	60 BBLS	Volume Recovered	60 BBLS
Source of Release	high pressure line	Date and Hour of Occurrence	8-28-13	Date and Hour of Discovery	8-28-13
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher		
By Whom?	Jerry Burton	Date and Hour	2:25 pm 8-28-13		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Im; acting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* discharge high pressure line split.  
Replaced high pressure line

Describe Area Affected and Cleanup Action Taken.\* on location east corner of private land.  
Cleaned up got permissions from land owners to dig out contaminated soil. Will have soil sampled, after cleared will be replaced with fresh top soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jerry Burton	Approved by Environmental Specialist:	Signed By <i>Mike Bratcher</i>	
Title: New Mexico Regional Dist Manager	Approval Date: SEP 20 2013	Expiration Date:	
E-mail Address: jerry.burton1961@gmail.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 8-29-13 Phone: 432-448-4917	Remediation per OCD Rule & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>		

\* Attach Additional Sheets If Necessary

*2RP-1916*  
**October 20, 2013**