

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

SEP 17 2013

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit a Copy to appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating 269324	Contact: Brian Wall	
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739	
Facility Name: HE West B 50	Facility Type: Oil Producer	
Surface Owner: Federal	Mineral Owner:	API No.: 3001527109

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	03	17S	31E	50	South	1400	West	Eddy

Latitude: 32.85653 Longitude: -103.86094

NATURE OF RELEASE

Type of Release: Produced Water / Oil	Volume of Release: 5.5bbls/ .5bbl	Volume Recovered: 0 / 0
Source of Release: 3" poly pipeline	Date and Hour of Occurrence: 09/09/2013 2:30pm	Date and Hour of Discovery: 09/09/2013 2:30pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Received call that pickup driven by Ferguson Pipeline Construction employee had driven off of road to get around truck performing pressure test on new pipeline. While crossing flowline undercarriage of pickup punctured hole in flowline for West B #50 well causing spill. Approx 6 barrels fluid released onto road and just off of road. Combination of oil and water. Approx 5.5 bbl water and .5 bbl oil. Shut in well. Used clamps to close off flowline

Describe Area Affected and Cleanup Action Taken.* : about 100ft x 50ft area affected. Remedial action pending.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Brian Wall

Title: Construction Foreman II

E-mail Address: bwall@linenergy.com

Date: 09/16/2013

Phone: 806-367-0645

OIL CONSERVATION DIVISION

Approved by District Supervisor:

Signed By

SEP 20 2013
Approval Date:

Expiration Date:

Conditions of Approval:

Remediation per OCD Rule & Guidelines, &

like approval by BLM. SUBMIT REMEDIATION

PROPOSAL NO LATER THAN:

October 20, 2013

Attached ☐

* Attach Additional Sheets If Necessary

2RP-1919