


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nJMW 1326254699

OPERATOR

Initial Report Final Report

Name of Company: Linn Operating <i>269324</i>	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Barclay Federal # 27	Facility Type: Oil Producer

Surface Owner: Federal	Mineral Owner:	API No.: 3001530883
------------------------	----------------	---------------------

LOCATION OF RELEASE

Unit Letter I	Section 01	Township 23S	Range 31E	Feet from the 1980	North/South Line South	Feet from the 660	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: 32.3315309423989 Longitude: -103.725142245464

NATURE OF RELEASE

Type of Release: Produced Water / Oil	Volume of Release: 5 bbls / 1 bbl	Volume Recovered: 0 / 0
Source of Release: 2 7/8" tubing ram	Date and Hour of Occurrence: 09/10/2013 10:00am	Date and Hour of Discovery: 09/10/2013 10:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton - BLM Mike Bratcher-NM OCD	
By Whom? Brian Wall	Date and Hour 09/11/2013 7:30am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: DROVE TO LOCATION TO CHECK WELL AND ARRIVED TO FIND 2-7/8 TUBING RAM LEAKING. SHUT UNIT DOWN TO STOP LEAK.

Describe Area Affected and Cleanup Action Taken.* : Remove contaminated soil and dispose of in approved waste facility

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brian Wall</i>	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by District Supervisor: Signed By <i>Mike Bratcher</i>	
Title: Construction Foreman II	Approval Date: SEP 19 2013	Expiration Date:
E-mail Address: bwall@linenergy.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, &	Attached <input type="checkbox"/>
Date: 09/11/2013 Phone: 806-367-0645	like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

October 19, 2013

2RP-1915