


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505



State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1325449742

Name of Company: BOPCO, L.P. <i>260737</i>		Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329
Facility Name: PLU-251H Flow line Spill is 981 ft. S.W. of well pad. GPS coord is at the spill location.		Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-34404
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	30	24S	30E					Eddy

Latitude N 32.184857 Longitude W 103.912405

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 2 Bbls oil and 10 Bbls produced water	Volume Recovered: None
Source of Release: 27/8" flow line	Date and Hour of Occurrence: Date 8/20/13 time unknown	Date and Hour of Discovery: Date 8/20/13 time 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The flow line developed a leak due to external corrosion. The section of pipe was replaced.

Describe Area Affected and Cleanup Action Taken.*
The spill stayed in the lease road area and traveled to the Regency Nash Draw Compressor site. Approximately 1500 sq. ft. of lease road and approximately 300 sq. ft. of compressor pad location. All of the fluid soaked into the ground. The road has had numerous reports of produced water being illegally dumped in the road way and compressor site. Soil samples were collected from various locations on the road on 9/10/13 to determine the extent of the release area and the existing chloride contamination due to illegal dumpings. A remediation plan will be submitted based on the findings of the sampling event.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: Signed By: <i>Mike Benjamin</i>	
Title: Waste Management and Remediation Specialist	Approval Date: SEP 11 2013	Expiration Date:
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: 9/10/13 Phone: 432-556-8730	<i>October 11, 2013</i>	<i>2RP-1903</i>

* Attach Additional Sheets If Necessary