

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
SEP 10 2013
NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1326036361 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Really Scary Federal Com #003H	Facility Type	Tank Battery

Surface Owner	Federal	Mineral Owner		Lease No. (API#)	30-015-36372
---------------	---------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	33	24S	28E					Eddy

Latitude 31.16772 Longitude 104.09347

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	80bbbls	Volume Recovered	75bbbls
Source of Release	Poly line	Date and Hour of Occurrence	09-05-2013	Date and Hour of Discovery	09-05-2013 6:30pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	09-08-2013 10:50am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Pipe stress and high pressure caused a hole in the poly line causing it to break off. Supported line better and lowered pressure.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 80bbbls of produced water were released due to a poly line failure caused by stress and high pressure. We were able to recover 75bbbls of produced water with a vacuum truck. The entire release was contained inside the lined facility. All free fluid has been recovered. Contaminated gravel has been removed and we have replaced with fresh gravel as necessary. This location has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature:	<i>Robert Grubbs Jr.</i>	Approved by District Supervisor:	Signed By <i>Mike Bratcher</i>
Printed Name:	Robert Grubbs Jr.	Approval Date:	SEP 17 2013
Title:	Senior Environmental Coordinator	Expiration Date:	
E-mail Address:	rgrubbs@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	09-10-2013	Phone:	432-661-6601

* Attach Additional Sheets If Necessary

2RP-1909