

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
SEP 10 2013  
NMOCD ARTESIA

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*njmw* 1326251610/COG Production OPERATOR  Initial Report  Final Report

Name of Company	COG OPERATING LLC 217955	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Sidewinder #001H	Facility Type	Tank Battery
Surface Owner	Private	Mineral Owner	Lease No. (API#) 30-015-38500

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	32	26S	29E					Eddy

Latitude 32.00143 Longitude 104.1374

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	20bbbls	Volume Recovered	15bbbls
Source of Release	4" metal lead line	Date and Hour of Occurrence	09-03-2013	Date and Hour of Discovery	09-03-2013 3:00pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A 1/4 inch hole developed in a 4" metal line. Replaced the 4" metal line with a plastic coated metal line.

Describe Area Affected and Cleanup Action Taken.\*  
Initially 20bbbls of produced water were released due to a 1/4 inch hole developed by corrosion. We were able to recover 15bbbls of produced water with a vacuum truck. The entire release was contained inside the lined facility. All free fluid has been recovered. Contaminated gravel has been removed and we have replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Grubbs Jr.	Approved by District Supervisor:	Signed By: <i>Mike Beaman</i>
Title: Senior Environmental Coordinator	Approval Date: SEP 19 2013	Expiration Date:
E-mail Address: rgrubbs@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 09-10-2013 Phone: 432-661-6601		

\* Attach Additional Sheets If Necessary

2RP-1913