Submit I Copy To Appropriate District State of New Mexico	Form C-103
District 1 – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVIS District III - (505) 224 (128)	5 Indicate Type of Lease
District III - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	VB-414
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	TO A 7. Lease Name or Unit Agreement Name Beauregard ANM State Com 8. Well Number
1. Type of Well: Oil Well Gas Well Other: P & A	1
2. Name of Operator Yates Petroleum Corporation	9. OGRID Number 025575
3. Address of Operator	10. Pool name or Wildcat
105 South Fourth Street, Artesia, NM 88210 4. Well Location	Red Lake; Atoka-Morrow
Unit Letter L : 1980 feet from the South line	and <u>660</u> feet from the <u>West</u> line
Section 14 Township 18S Range 27E NMPM Eddy County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
11. Elevation (Show whether DR, RKB, R 3475' GR	1, GR, <i>ElC.)</i>
12. Check Appropriate Box to Indicate Nature o	•
	SUBSEQUENT REPORT OF: DIAL WORK
	IENCE DRILLING OPNS. P AND A
OTHER: OT	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
8/25-27/13 - Pumped 280 bbls of calcium down 7" casing. Pumped 40 bbls down tubing. ND tree. NU BOP. Latched onto fish at	
6604'. Tubing is free all the way down to 9492'. RIH w/ chemical cutter to 9490'. Cut 2-3/8" tubing did not pull free. RIH with jet cutter at 9485'. Cut 2-3/8" tubing, worked tubing loose. Set CIBP on top of fish at 9485'. Left 2 joints, packer, on/off tool and 2' piece	
in the hole = 78'. RIH w/ 3.62" GR and JB to liner top at 7304'. Tagged at 7349' then tagged at 9461'.	
8/29-9/2/13 – Set CIBP at 8909' did not go further. RIH w/ 3.63" GR and JB to work down to 9460'. POH at liner top, pull heavy, work free. RIH w/ wireline. Set CIBP. Could not go in the liner top. RIH w/ 3.62" GR and JB. Could not get inside liner top at 7304'. Per	
Randy Dade w/ NMOCD, RIH open ended tubing to 9466'. Spotted 25 sacks (5.2 bbls - 329') Class "H" plug across Morrow top. TOC	
approximately 9137'. Spotted 50 sacks (10.5 bbls – 467') Class "H" plug across liner top. TOC approximately at 7164'. Pumped 50 bbls down 7" casing. Tagged cement liner top at 7105'. Pulled up and set RBP test tools to 1500#, good.	
Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) for final inspection <u>CONTINUED ON NEXT PAGE</u> :	
which may be found at OCD Web Page under	
Spud Date: Rig Release Date:	
	SEP 26 2013
I hereby certify that the information above is true and complete to the best of my	knowledge and belief.
SIGNATURE DATE DATE TITLE <u>Regulatory Reporting Technician</u> DATE <u>September 25, 2013</u>	
Type or print name <u>Laura Watts</u> E-mail address: <u>laura@yatespetroleum.com</u> PHONE: <u>575-748-4272</u> <u>For State Use Only</u>	
APPROVED BY: TITLE TITLE DIST Screwers DATE 9/30/13	
* Submitt Subsequent C-103 For Plugging	

Form C-103 continued:

9/3-7/13 – Found good casing from 3587' up to surface – good for 1000#. Could not get past tight spot at 6635' Set cement retainer to 3548'. Pumped 20-1/2 bbls of calcium mud thru retainer. Set retainer at 3548'. Loaded 7" casing w/ 9 bbls. Tested to 1000#, good. Pumped down 9-5/8" casing. Pumped 140 bbls of brine. WOC.

9/8-10/13 - Sting out of retainer. Displaced hole w/ 135 bbls of fresh water. Sting into retainer. Pumped down 9-5/8". Pumped 1100 sacks (259 bbls) Class "C" cement at 14.8#. Shut down on vacuum. Pumped 26 bbls of Class "C" cement. Cement coming out of 9-5/8" Squeeze well to 1500# w/ 404 sacks (95 bbls) Class "C" cement at 14.8#. Sting out of retainer. Reversed out 92 sacks (20.5 bbls) of cement. RIH with CCL/GR/CBL log from 3548' to surface with 500#. Tubing at 3548'. Displaced hole w/ 135 bbls brine mud gel. Spotted 25 sacks of Class "C" cement plug on top of retainer. Approx TOC at 3399'. Spotted 30 sacks Class "C" cement plug across 9-5/8" shoe at 2190'. WOC. Tagged at 9-5/8" shoe. Cement top at 2066'. As per OCD, spotted 72 sacks (17 bbls) Class "C" cement to surface. ND BOP. Topped off cement inside 7" casing.

9/18/13 – Dug up cellar and cut off all wellheads. Installed dry hole marker as per NMOCD. Cover cellar and cut off anchors. Cleaned location. <u>WELL IS PLUGGED AND ABANDONED</u>.

Regulatory Reporting Technician /September 25, 2013