·		
Submit 3 Copies Appropriate District Office State of New Mexico	Form October 2	C-103
	WELL API NO.	.5, 2005
1625 N. French Dr., Hobbs, NM 88240 CEIVED	30-015-22750	1
District II 1301 W. Grand Ave., Artesia NM 88ALDG 29 MORE CONSERVATION DIVISION	5. Indicate Type of Lease	,
Disrtict III 1000 Rio Brazos Rd. Aztec, NASTICO ARTESIA, 1320 South St. Francis Dr.	STATE 🗹 FEE 🗌	
District IV Santa Fe, NM 8/505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Empire Abo Unit "I"	
PROPOSALS.)	8. Well Number	
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator	251 9. OGRID Number	
Apache Corporation	00873	
3. Address of Operator	10. Pool Name	
303 Veterans Airpark Lane, Ste. 3000, Midland, TX, 79705 4. Well Location	Empire Abo	
Unit Letter D : 660 feet from the N line and	150 feet from the W line	
Section 5 Township 18S Range 28E 11. Elevation (Show whether DR, RKB,RT, GR, etc.)	NMPM County E	ddy
3673' GR		
12. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	SUBSEQUENT REPORT OF: ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
DOWNHOLE COMMINGLE		
	eady for OCD inspection after P&A	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from the lease and well location.		
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.) All other environmental concrens have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All flu	ids have been removed from	
non-retrieved flow lines and pipelines.		
When all work has been completed, return this form to the appropriate District office to schedule an in		
inspection has to be made to a P&A location because it does not meet the criteria above, a penalty n	nay be assessed.	
SIGNATURETITLEP&A Technici	an DATE 8/21/13	
TYPE OR PRINT NAME Leon Sellers E-MAIL leon.sellers@apache	ecorp.com PHONE: 432-208-03	49
APPROVED BY: Jink. Stem TITLE C. C.	1/1/1/	. 2
Conditions of Approval (if any):	DATE	2
OK. TO RELEASE.		