


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505



State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
220 S. St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NJM 1328128519

Name of Company Devon Energy		6/37	OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address PO Box 250 Artesia, NM 88211			Contact Dan Suniga		
Facility Name Black Jack 1 Fed 4H			Telephone No. 575-390-5850		
			Facility Type Oil		
Surface Owner		Mineral Owner		API No. 30-015-37065	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	1	24S	30E	330	SOUTH	2230	WEST	EDDY

Latitude: 32.2405799853399 Longitude: -103.835714231733

NATURE OF RELEASE

Type of Release: Spill	Volume of Release 8bbl Oil/2bbl PW	Volume Recovered 1/2bbl Oil - 1/2bbl PW
Source of Release: Flow line leak	Date and Hour of Occurrence 10/3/13 09:00am	Date and Hour of Discovery 10/3/13 09:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Matt Howell-Lease Operator Don Mayberry-Superintendent Mike Brasher-NMOCD Dan Suniga-Foreman Scott Poe-EHS Kim Ames-BLM	
By Whom? Hubert Perry	Date and Hour: 10/3/13 10:30am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Approximately 9 am October 3rd Supervisor for the Black Jack 1 Fed 4H was contacted by Banta gang and informed him of a flow line leak on top of the pipe. Supervisor advised to shut well in and isolate area because of cattle in the pasture.

Describe Area Affected and Cleanup Action Taken.*

It occurred on a steep incline therefore the area affected was 466ft x 2ft due to it flowing down the side of the incline. 8bbls PW and 2bbls Oil were spilled. Notified vacuum truck to pick up spill (1/2bbl PW/ and 1/2bbl of Oil recovered) and contacted all necessary personnel.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Veronica Teel	OIL CONSERVATION DIVISION	
Printed Name: Veronica Teel	Approved by Environmental Specialist: <i>Mike Brasher</i>	
Title: Field Admin Support	Approval Date: OCT 08 2013	Expiration Date:
E-mail Address: Veronica.Teel@dvn.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: October 3, 2013	Phone: 575-748-9933	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

November 8, 2013

2RP-1978