				F 0.400
Submit 3 Copies To Appropriate District Office	State of N	ew Mexico		Form C-103 October 25, 2005
District I			WELL API NO.	
1625 N French Dr. Hobbs, NM 88240			30-015-01662	
District II 1301 W. Grand Ave., Artesia, NM 88210335 OCD OIL CONSERVATION DIVISION District III			5. Indicate Type of Lease	
Disrtict III		, STATE 🗹		
1000 Rio Brazos Rd. Aztec, NM 87410	9 2013 1220 South S	St. Francis Dr.	6. State Oil & Gas Lease	
1000 Rio Brazos Rd. Aztec, NM 87410       2 9 2013       1220 South St. Francis Dr.         District IV       JUL 2 9 2013       Santa Fe, NM 87505         1220 S. St. Francis Dr., Santa Fe, NM       Santa Fe, NM 87505			0. State Oli & Gas Lease	INU.
87505	-nrED /		· · ····	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Empire Abo Unit "G"	
PROPOSALS.)			8. Well Number	
1. Type of Well: Oil Well 🔽 Gas Well 🗌 Other			25	
2. Name of Operator			9. OGRID Number	
Apache Corporation 3. Address of Operator			00873 10. Pool Name	
	ane, Ste. 3000, Midland,		Empire	Abo
4. Well Location				
Unit Letter L	: 990 feet from the	W line and	1650 feet from the	S line
Section 32	Township <b>17S</b> 1. Elevation ( <i>Show whether</i>		NMPM	County Eddy
	-	<b>3676'GR</b>		
12. Check Appropriate Box To Indica			Alarge an information Market and Market	an a "Anata Sahi <u>handi ada ina babili ba a</u> habili ba <u>Anaja an ang ang ang an</u> g ang ang ang ang ang ang ang ang a
	UUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING OP CASING/CEMENT JOB	NS. P AND A	
OTHER:		✓ Location is re	adv for OCD inspection at	tor P&A
OTHER:       Image: Construction of the constr				
<ul> <li>Rat hole and cellar have been filled and</li> <li>A steel marker at least 4" in diameter and</li> </ul>				
	SE NAME, WELL NUMBER			IN OR
	I, TOWNSHIP, AND RANGE ED ON THE MARKER'S SU			Con Claud
		ENION -	• • • • • •	4 OU GROUND.
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. $M = M = M = M = M = M = M = M = M = M $				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operato from the lease and well location.	r's pit permit and closure plan.	All flow lines, production equi	oment and junk have been re	emoved
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.)				
<ul> <li>✓ All other environmental concrens have been addressed as per OCD rules.</li> <li>✓ Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from</li> </ul>				
non-retrieved flow lines and pipelines.				
When all work has been completed, retuin inspection has to be made to a P&A location has the second secon				
		le ciliena above, a penaity in	ay be assessed.	
SIGNATURE Zen Lulu	TITLE	P&A Technici	anDATE	7/24/13
	Sellers E-MAIL	leon.sellers@apache	<u>corp.com</u> PHONE:	432-208-0349
For State Use Only		$\Omega$		
APPROVED BY:	TITLE	YENICH	DATE	10/23/13
Conditions of Approval (if any):	ist.			V
•				