


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

132903 5080

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Lost Tank 10 Federal #2	Facility Type	Well location

Surface Owner	BLM	Mineral Owner		API No.	30-015-37960
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	3	22S	31E	840	South	1838	East	Eddy

Latitude N 32.415595°

Longitude W 103.763146°

NATURE OF RELEASE

Type of Release	Oil and Produced Water	Volume of Release	10 bbls oil, 5 bbls produced water	Volume Recovered	0 bbls
Source of Release	4" needle valve on circulating line broke off	Date and Hour of Occurrence	10/01/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; Jennifer Van Curen-BLM		
By Whom?	Chancey Summers	Date and Hour	10/07/2013 @ 10:14 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Area livestock have been rubbing the circulating line causing the 4" needle valve to break off and allow 10 bbls of oil and 5 bbls of produced water to leak onto the ground. No fluids were recovered and the valve was repaired/replaced.

Describe Area Affected and Cleanup Action Taken.*

The area affected was approximately 20' x 40' with all of the leak staying on location. Remediation will be conducted in accordance with a plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Chancey Summers

Title: HES Specialist

E-mail Address: Chancey.Summers@oxy.com

Date: 10/15/13

Phone: (575) 397-8216

Approved by Environmental Specialist

Signed By

Mike Bratcher

OCT 17 2013

Approval Date:

Expiration Date:

Conditions of Approval:
Remediation per OGD Rule & Guidelines, &
like approval by BLM. **SUBMIT REMEDIATION**

Attached ☐

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

November 17, 2013

2RP-1996