

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

NOV 12 2013

NMOC D ARTESIA

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

nTJW 1331842147

27484/OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ALAMO PERMIAN RESOURCES, LLC	Contact	RICKY RODRIGUEZ
Address	415 W. WALL ST. SUITE 500	Telephone No.	575 703 6425
Facility Name	COWTOWN UNIT 202	Facility Type:	Oil Well

Surface Owner	STATE	Mineral Owner		API No.	30-015-41018
---------------	-------	---------------	--	---------	--------------

### LOCATION OF RELEASE

Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
13	18S	26E	700	S	810	W	EDDY

Latitude 32.7429997421485

Longitude -104.135830720785

### NATURE OF RELEASE

Type of Release: OIL	Volume of Release: 15 BBLS	Volume Recovered: 11 BBLS
Source of Release: FRAC TANK	Date and Hour of Occurrence: NOV 12, 2013	Date and Hour of Discovery: NOV 12, 2013
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER via phone call	
By Whom? Carie Stoker	Date and Hour Nov 12, 2013, 2:52 P.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Frac Tank overflow (temporarily producing into frac tank while awaiting installation of new heater treater); vacuum truck dispatched to recover standing oil

Describe Area Affected and Cleanup Action Taken.\*

Clean up action: A backhoe was dispatched to scrape up leak affected earth, which will be hauled to a disposal facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: CARIE STOKER		Approved by Environmental Specialist: Signed By 	
Title: REGULATORY AFFAIRS COORDINATOR		Approval Date: NOV 14 2013	Expiration Date:
E-mail Address: carie@stokeroilfield.com		Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: December 14, 2013	Attached <input type="checkbox"/>
Date: 11/12/2013	Phone: 432 664 7659		

\* Attach Additional Sheets If Necessary

2RP-2063