Tabilit I Copy To Appropriate District State of New Mexico	Form C-103
District I – (575) 393-6161 Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	30- Dい 5- 3233 く 5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> - (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	VA-1221
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	-
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	McMillan 24 state
1. Type of Well: Oil Well Gas Well Other	8. Well Number 2
2. Name of Operator	9. OGRID Number
OXY USA Inc.	16696
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 50250 Midland, TX 79710	McM: 16 n Wolfcamps (Gas)
4. Well Location	
Unit Letter <u>1</u> : <u>1930</u> feet from the <u>south</u> line and <u>930</u> feet from the <u>east</u> line	
Section 24 Township 205 Range 26E	NMPM County Edge
11. Elevation (Show whether DR, RKB, RT, GR, etc. 3293 GR)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
12. Check Appropriate box to indicate Nature of Notice, Report of Other Data	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK 🔲 PLUG AND ABANDON 🔲 🛛 REMEDIAL WOR	K 🔲 ALTERING CASING 🗍
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR	— — —
PULL OR ALTER CASING 🔲 MULTIPLE COMPL 🔲 CASING/ÇEMEN	т јов
CLOSED-LOOP SYSTEM	back, Recompletion
13. Describe proposed or completed operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co	
proposed completion or recompletion.	
See Attached	RECEN
See Attachec	JAN 30 2014
	JAN 30 2011
	NAAQQ
	CHIMOCD ARTES
	ALCONA (
· · · · · · · · · · · · · · · · · · ·	
Spud Date: Rig Release Date:	
Spud Date.	
I hereby certify that the information above is true and complete to the best of my knowledge	re and belief
Thereby certify that the information above is the and complete to the best of my knowledg	
SIGNATURE DATE 1/27/14	
Type or print name <u>David Stewart</u> E-mail address: <u>david_stewart@oxy.com</u> PHONE: <u>432-685-5717</u>	
For State Use Only $\rho \rightarrow 1$	
$\int \int d d = \int d d d = \int d d d = \int d d d d d d d d d d d d d $	
APPROVED BY	
Conditions of Approval (if any):	
	· /

,

Mc 1illan:24 State #2 - 30-015-32336

Date Remarks


- 1/12/12 MI RU, 700#-CSG/TBG. FLOW BACK TBG TO REVERSE TANK RECOVERED 70 BBLS OF WELL FLUID. FLOW BACK CSG TO REVERSE TANK RECOVERED 150 BBLS OF WELL FLUID. PUMP 120 BBLS FW. NDWH, NUBOP, START TO POOH & SCAN W/ 2-7/8" N-80 TBG.
- 1/13/12 170# -CSG/TBG. BLEED OFF CSG & TBG TO REVERSE TANK RECOVERD 40 BBLS OF WELL, FLUID FROM TBG & CSG HAD STRONG GAS BLOW. PUMP 100 BBLS 10# BRINE TO KILL WELL. CONTINUE TO POOH & SCAN TBG, TOTAL 170 JTS - 2-7/8" N-80 TBG, 10 JTS - 2-3/8" N-80 TBG. START TO RIH W/ 4-1/8" BIT, CSG SCRAPER, 2-7/8" N-80 TBG.
- 1/16/12 130# CSG/TBG. BLEED OFF TBG & CSG, CSG HAD STRONG GAS BLOW. PUMP 50 BBLS FW TO KILL WELL. CONTINUE IN HOLE, TAG 5" LINER TOP @ 8873', ATTEMPT TO RUN BIT & CSG SCRAPER THROUGH LINER TOP WITH NO LUCK, POOH.
- 1/17/12 10# CSG/TBG. PUMP 30 BBLS FW DOWN CSG TO KILL WELL. FINISH POOH W/ TBG, BHA. RU ROTARY WL, RIH W/ 5" GAUGE RING & JUNK BASKET TO 10300', POH WITH GAUGE RING. RIH W/ 5" CIBP & SET @ 10250', POOH W/ WL, LD SETTING TOOLS. RIH W/ DUMP BAILER & DUMP 50' CMT ON CIBP TO 10200', POOH W/ DUMP BAILER, RD WL. LOAD CSG W/ 105BBLS FW, THEN ATTEMPT TO PRESSURE TEST CSG TO 500# W/ NO LUCK, THE AVERAGE RATE WAS 2 BPM W/ 600# BACK PRESSURE, ISIP-0. DIG OUT WH FOUND 9-5/8" SURFACE VALVE, CHECKED PRESSURE FOUND 0#, LEFT VALVE OPEN. LOAD CSG AGAIN W/ 69BBLS FW, EIR @ 2 BPM W/ 600# BACK PRESSURE, PUMP A TOTAL OF 30 BBLS, NEVER GOT RETURNS AT 9-5/8" BRADENHEAD.
- 1/18/12 RIH W/ 7" PKR & SET @ 8798', PUMP DOWN TBG, LOAD CSG W/ 17 BBLS FW. PRESSURE TEST 5" LINER TO 500# FOR 20 MINS WITH GOOD TEST. LOAD 7" CSG W/ 135 BBLS FW & ATTEMPT TO PRESSURE TEST CSG TO 500# W/ NO TESTK, AVERAGE RATE WAS 2 BPM WITH 600# BACK PRESSURE. UNSET PKR & START TO ISOLATE CSG LEAK @ 1000' @ A TIME, SET PKR @ 6255' WITH A TOTAL OF 200 JTS IN THE HOLE. PRESSURE TEST CSG UP TO 500# W/GOOD TEST FROM 6255' TO SURFACE.
- 1/19/12 MOVE PKR THEN CONTINUE TO ISOLATE CSG LEAK. FOUND CSG LEAK @ 8298-8330' EIR @ 2.5 BPM @ 650#, PRESSURE RISES WHEN RATE IS INCREASED. UNSET PKR & POOH. RIH W/ 2-7/8" N-80 TBG OPEN ENDED.
- 1/20/12 CONTINUE RIH W/ 2-7/8" TBG OPEN ENDED, RU RISING STAR, M&P 35sx CL H CMT, WOC 5 HRS. RIH W/ 2-7/8" TBG, DIDN'T TAG ANITHING, PUH TO 8000'.
- 1/21/12 POH W/ 2-7/8" TBG, LD BOTTOM 26 JTS, CAME OUT FULL OF CMT. RU ROTARY WL, RIH W/ 2" WEIGHT BAR, TAG FLUID @ 2000' FROM SURFACE, TAG CMT @ 10202', POOH W/ WL. RIH W/ 2-7/8" TBG OPEN ENDED TO 9005'.
- 1/23/12 RU RISING STAR, M&P 35sx CL H CMT FROM 9000' TO 8823', PUH 945' ABOVE CEMENT, WOC 5 HRS. RIH W/ 2-7/8" TBG, TAG CMT @ 8818', PUH TO 8786', SPOT 35 BBLS 10# MUD FROM 8818' TO 8275', POOH. RU ROTARY WL, RIH W/ 7" CIBP & SET @ 8275', POOH. LOAD CSG W/ 81 BBLS FW, PRESSURE UP ON 7"CSG TO 500# FOR 30 MIN W/ GOOD TEST.
- 1/24/12 RIH W/ WL & PERF 4SPF, .48" @ 7890-7920, 7944-7954, 8004-8022, 8076-8090' TOTAL 234 HOLES, RD WL. RIH W/ RBP & PKR ON 2-7/8" TBG.
- 1/25/12 RIH & SET RBP @ 8108' & PKR @ 8058'. ACIDIZE W/ 2000 GALS 17.5% HCL ACID @ 2.5 BPM W/ MAX PRESSURE @ 2680# W/ ISIP-660#. PUH & SET RBP @ 8038' & PKR @ 7988', ACIDIZE W/ 3000 GALS 17.5% HCL ACID @ 3.3 BPM W/ MAX PRESSURE @ 1740# W/ ISIP-650#. PUH & SET RBP @ 7974' & PKR @ 7924', ACIDIZE W/ 2000 GALS 17.5% HCL ACID AT 4 BPM W/ MAX PRESSURE @ 2050# W/ ISIP-820#. PUH & SET RBP @ 7930' & PKR @ 7880', ACIDIZE W/ 5000 GALS 17.5% HCL ACID AT 5 BPM W/ MAX PRESSURE @ 2040# w/ ISIP-880#, BLEED OFF PRESSURE, OPEN TBG & FLOW BACK 150 BBLS OF WATER AND ACID.
- 1/26/12 850# TBG/CSG, OPEN TBG & FLOW BACK 375 BBLS OF WATER, OIL & GAS W/ 100# BACK PRESSURE ON TBG AND CSG. THERE WAS A 30% OIL CUT ON SAMPLES COLLECTED.
- 1/27/12 250# -TBG, BLED OFF PRESSURE, UNSET PKR, EQUALIZE PRESSURE, RIH TO RBP, UNLATCH, CIRC 260 BBLS 7% KCL WTR, POOH & LD. RIH W/ 2 MUD ANCHOR JTS W/ BULL PLUG, 4' x 2-7/8" PERF SUB, 2-3/8" STD SN, 4 JTS 2-7/8" N-80 TBG, 7" 45K TAC, 2 JTS 2-7/8" TBG, 2' X 2- 7/8" TBG MARKER SUB N-80. 252 JTS 2-7/8" N-80 TBG.
- 1/28/12 ND BOP, SET TAC @ 7848', NU WH, CONNECT TO FLOWLINE. SI WO ON RODS
- 1/30/12 RIH W/ 12' x 1" GAS ANCHOR, 20-125-RHBC-24-4 PUMP, 4-1-1/4' KB, 140-3/4" D-90 STEEL RODS, 106-7/8" D-90 STEEL RODS, 71-1" D-90 STEEL RODS, PU 2' x 1" PONY SUB THEN INSTALL 26' x 1-1/2" POLISH ROD. PU & HANG ON PUMPING UNIT HEAD. SPACE OUT PUMP 8" OFF BOTTOM. LOAD TBG W/ 1 BBL OF 7% KCL WATER THEN TEST TBG TO 500# W GOOD TEST, BLEED OFF PRESSURE. LONG STROKE PUMP, 5 STROKES TO 500 PSI (GOOD) BLEED OFF PRESSURE.

1/31/12 RD PU, REVERSE UNIT, PUMP WELL ON PUMP AND TEST.

OXY USA Inc. - Current McMillan 24 State #2 API No. 30-015-32336

•

ų....



1-1/4" X 24' rod pump

2-7/8" tbg @ 7862' w/ TAC @ 7848'

CIBP @ 8275'

35sx @ 9000-8818' Tagged

CIBP @ 10250' w/ 5sx to 10200' Tagged

ł