

RECEIVED
MAR 13 2014
NMOCD ARTESIA

PDistrict I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
70 Rio Brazos Road, Aztec, NM 87410
District IV
20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
P
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nHP 1608433913

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Repo
Name of Company	COG OPERATING LLC 229137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Burch Keely Unit #232	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-015-27992

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	23	17S	29E					Eddy

Latitude 32.81382 Longitude 104.04572

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	80bbls	Volume Recovered	75bbls
Source of Release	Transfer filter pot	Date and Hour of Occurrence	02-22-2014	Date and Hour of Discovery	02-22-2014 05:15am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	02-24-2014 3:332pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Valve was not completely closed which caused the hose to pressure up enough to pop loose the connection on the bottom of the filter pot. Hose will be replaced and valve closed completely.

Describe Area Affected and Cleanup Action Taken.*

Initially 80bbls of produced water were released. We were able to recover 75bbls with a vacuum truck. All free fluids have been recovered Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION	
Signature:	Approved by District Supervisor:
Printed Name: Robert Grubbs Jr.	Title: Senior Environmental Coordinator
Title: Senior Environmental Coordinator	Approval Date: 3/25/14 Expiration Date: NA
Email Address: rgrubbs@concho.com	Conditions of Approval:
Date: 03-06-2014 Phone: 432-661-6601	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines, &
like approval by BLM. **SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:**
9-25-14

2 RP-2220