District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

## State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1220 S. St. Fran	icis Dr., Santa	a Fe, NM 8/50:	,	Sa	anta F	e, NM 875	505					
			Rele	ease Notific	catio	n and Co	orrective A	ction				
						OPERA?	ГOR		ıl Report	Final Rep	or	
Name of Company Burnett Oil Co. Inc. 308-0						Contact Sh	Contact Shawna Matthews					
		8, Loco Hill				Telephone No. (575) 322-7213						
							Facility Type Gas Line					
Surface Owner BLM Mineral Owner							API No. 30-015-32793					
						ATTNO. 30-013-32/93						
	T	1 =				N OF RE						
Unit Letter	Section	Township	Range	Feet from the	North	n/South Line	Feet from the	East/West Line	County			
L	13	17S	30E	1730		FSL	1098	FWL	Eddy			
			Latituda	e 32.831953	Lor	ngitude <u>-10</u>	3 930483					
			Latria	<del>-</del>		_						
T CD 1	0.1	10 1 10		NAI	URE	OF REL		17.1 B	1.0			
Type of Release Oil and Produced Water Source of Release Multiple poly lines							Release 5 bbls  Hour of Occurrence					
Source of Resease Multiple pory files							0:30 am	3/24/14 10:30 am				
Was Immediate Notice Given?						If YES, To Whom?						
☐ Yes ☐ No ☐ Not Required						Mike Burton - BLM						
By Whom? Jake Kamplain - RECS							Date and Hour 3/24/14 1:05 pm					
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
IC W							r	BEAER				
If a Watercourse was Impacted, Describe Fully.*								RECEIV	/EU	1		
							1	MAR 27	) n 14			
								WANZI	-011			
Describe Cause of Problem and Remedial Action Taken.*								NMOCD AR	TESIA		_	
A rupture in	A rupture in a gas line caused a fire that melted several poly lines releasing oil and produced water over 9,274 square feet of pasture land. None of this											
fluid was rec	overed. Th	e lines were s	hut down	and repaired.								
Describe Are	ea Affected	and Cleanup	Action Tal	ken.*				<u> </u>				
Describe Area Affected and Cleanup Action Taken.*  The site will be assessed and then remediated to NMOCD and BLM regulations.												
							•					
								nderstand that purs				
								tive actions for rele				
								eport" does not reli eat to ground water				
								responsibility for co				
		ws and/or regi			·					<u> </u>		
(	$\rightarrow$	100		/			OIL CON	<u>SERVATION</u>	DIVISIO	<u>)N</u>		
Signature:	Snaw	ro Ma	tthei	4				4	1			
						Approved by Environmental Specialist:						
Printed Name	e: Shawna	Matthews						tju	1 cm		_	
Title: Production Technician							Approval Date: 4-2-14 Expiration Date: NA					
			'1					1 1				
E-mail Addre	ess: smatth	ews@burnetto	oil.com			Conditions of	t Approval:		Attached			

\* Attach Additional Sheets If Necessary

Phone: (575) 322-7213

Remediation per OCD Rule &

Guidelines. **SUBMIT REMEDIATION** 

PROPOSAL NO LATER THAN:

2RP-2243