

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company <b>COG Operating LLC</b>	Contact <b>Pat Ellis</b>	
Address <b>550 W. Texas, Suite 1300 Midland, Texas 79701</b>	Telephone No. <b>(432) 230-0077</b>	
Facility Name <b>BKU Central Tank Battery</b>	Facility Type <b>Tank Battery</b>	
Surface Owner <b>Federal</b>	Mineral Owner	Lease No. <b>30-015-29809</b>



#### LOCATION OF RELEASE

Unit Letter <b>P</b>	Section <b>23</b>	Township <b>17-S</b>	Range <b>29-E</b>	Feet from the	North/South Line	Feet from the	East/West Line	County <b>Eddy</b>
-------------------------	----------------------	-------------------------	----------------------	---------------	------------------	---------------	----------------	-----------------------

Latitude N 32 49.161° Longitude W 104 01.546°

#### NATURE OF RELEASE

Type of Release: <b>Oil</b>	Volume of Release <b>120 bbls</b>	Volume Recovered <b>115 bbls</b>
Source of Release <b>Oil Tank</b>	Date and Hour of Occurrence <b>12/03/2011</b>	Date and Hour of Discovery <b>12/03/2011 6:00 a.m.</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Mike Bratcher - OCD</b> <b>Jim Amos - BLM</b> <b>Terry Gregston - BLM</b>	
By Whom? <b>Josh Russo</b>	Date and Hour <b>12/05/2011 8:48 a.m.</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>N/A</b>	
If a Watercourse was Impacted, Describe Fully.* <b>N/A</b>		
Describe Cause of Problem and Remedial Action Taken.* <b>A hole developed in an oil tank at the facility causing the release. The tank was isolated and has been prepared for repairs.</b>		
Describe Area Affected and Cleanup Action Taken.* <b>Tetra Tech inspected and collected samples to define spill extents. Soil with elevated chloride concentrations was removed and transported to Controlled Recovery, Inc. for proper disposal. Once excavated to the appropriate depths, the site was backfilled with clean soil and then brought up to surface grade. Tetra Tech prepared and submitted the closure report to NMOCD for review.</b>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Ike Tavarez (agent for COG)</b>		Approved by District Supervisor: 	
Title: <b>Project Manager</b>		Approval Date: <b>APR 17 2014</b>	Expiration Date: <b>NA</b>
E-mail Address: <b>ike.tavarez@tetrattech.com</b>		Conditions of Approval: <b>Final</b>	
Date: <b>8/15/12</b> Phone: <b>(432) 682-4559</b>		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary