OCD Artesia DCD Artesia UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side. Type of Well O Oil Well O Gas Well O ther Name of Operator Contact: ROSALINDA COBOS	FORM APPROVED         OMB NO. 1004-0135         Expires: July 31, 2010         5. Lease Serial No.         NMLC068431         6. If Indian, Allottee or Tribe Name         7. If Unit or CA/Agreement, Name and/or 1         891000303X         8. Well Name and No.         POKER LAKE UNIT 322H         9. API Well No.         30-015-40791-00-S1
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.         SUBMIT IN TRIPLICATE - Other instructions on reverse side.         Type of Well         Image: Other image: O	<ul> <li>5. Lease Serial No. NMLC068431</li> <li>6. If Indian, Allottee or Tribe Name</li> <li>7. If Unit or CA/Agreement, Name and/or I 891000303X</li> <li>8. Well Name and No. POKER LAKE UNIT 322H</li> <li>9. API Well No. 30-015-40791-00-S1</li> </ul>
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side. Type of Well O Oil Well Gas Well Other	<ul> <li>6. If Indian, Allottee or Tribe Name</li> <li>7. If Unit or CA/Agreement, Name and/or 1 891000303X</li> <li>8. Well Name and No. POKER LAKE UNIT 322H</li> <li>9. API Well No. 30-015-40791-00-S1</li> </ul>
Type of Well Gas Well Other	891000303X 8. Well Name and No. POKER LAKE UNIT 322H 9. API Well No. 30-015-40791-00-S1
🛛 Oil Well 🔲 Gas Well 🔲 Other	POKER LAKE UNIT 322H 9. API Well No. 30-015-40791-00-S1
	30-015-40791-00-S1
BOPCO LP E-Mail: rcobos@basspet.com	
a. Address 3b. Phone No. (include area code) Ph: 432.683.2277	10. Field and Pool, or Exploratory NASH DRAW DEL/BS
MIDLAND, TX 79702 Location of Well (Footage, Sec., T., R., M., or Survey Description)	11. County or Parish, and State
Sec 5 T24S R30E SENE 1130FSL 280FEL	EDDY COUNTY, NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTIC	CE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTI	ION
□ Notice of Intent	Production (Start/Resume) 🔲 Water Shut-(
C Subsequent Penert	Reclamation 🔲 Well Integrit
□ Final Abandonment Notice □ Change Plans □ Plug and Abandon □ To	Cemporarily Abandon Drilling Operation Vater Disposal
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Requi following completion of the involved operations. If the operation results in a multiple completion or recompletio testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including recli determined that the site is ready for final inspection.) 01/05/2014 ? SPUD. 01/06/2014 ? Drilled 17-1/2" hole to 617'. Ran 15 jts 13-3/8", 54.5#, J-55, STC set at 617?.	ired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed onc lamation, have been completed, and the operator has 4/14/14 Accordect for focord
<ul> <li>- 350 sks Econocem C, followed by Tail - 350 sks of Halcem C. Circulated 325 sks to half t WOC 24 hrs.</li> <li>01/07/2014 ? Test pipe rams &amp; annular with both 4" and 4-1/2" drill pipe. Test blind rams, revalves and choke manifold to 250 psi low and 3,000 psi high. All test held for 10-mins. Test and lower top drive valves, TIW floor valve, IBOP valve, rotary hose, stand pipe valves and lines back to mud pumps to 250 psi low and 3,000 psi high. An accumulator and function te done by Battle testers. All test recorded on chart. Test 13-3/8? casing to 1,918 psi. All goot tests.</li> </ul>	tank. elated t upper d mud est was APR <b>1 6</b> 2014
4. I hereby certify that the foregoing is true and correct. Electronic Submission #238343 verified by the BLM Well Inform For BOPCO LP, sent to the Carlsbad Committed to AFMSS for processing by JAMES AMOS on 04/12/20 Name (Printed/Typed) JEREMY BRADEN Title ENGINEERIN	•
	· · · · · · · · · · · · · · · · · · ·
Signature     (Electronic Submission)     Date     03/10/2014       THIS SPACE FOR FEDERAL OR STATE OFFIC	CE USE
	<u> </u>
Approved By ACCLFILD	Date 04/12
le 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfull States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.	ly to make to any department or agency of the United
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **	/ISED ** BLM REVISED **

1

ł.

.

.

## Additional data for EC transaction #238343 that would not fit on the form

## 32. Additional remarks, continued

01/10/2014 ? Drilled 12-1/4" hole to 3,735'. Ran 82 jts 9-5/8", 40#, J-55, LT&C, MU and landed mandrel in Cameron Mulit-Bowl Wellhead set at 3,724'. Lead - 1,100 sks Econocem HCL, followed by Tail - 300 sks Cemex Premium Plus C. Circulated 366 sks to surface. Full returns throughout job. Packed seals on MBS to 6,500 psi and test hanger mandrel void to 5,000 psi. Good test.

01/11/2014 ? Test 9-5/8? casing to 2,765 psi. Good test. WOC 24 hrs.

01/17/2014 ? Drilled 8-3/4? hole to 7,747?. Ran 182 jts 7", 26#, HCP-110, LTC set at 7,734', MU and landed mandrel in Cameron Multi-Bowl Wellhead'. Float collar at 7,650? and DV tool set at 5,008?. Stage 1: Lead - 270 sks Tuned Light, followed by Tail - 120 sks Versacem H. Full returns throughout job. Drop DV opening dart and pressure up to 800 psi to open DV tool. Circulated 60 . bbls FW with red dye to surface, but had no cement. Stage 2: Lead - 400 sks Tuned Light, followed by Tail ? 250 sks Premium Plus C. Pressured up to 2,458 to close DV tool. Tool closed. Full returns throughout job. Red dye and 88 sks cement circulated surface.

01/19/2014 ? MU Weatherford's test plug to test pack-off bushing in MBS, test plug would not hold, changed "O" rings, but still would hold, LD test plug, closed blind rams, pressure tested pack-off bushing "P" seals & 7" casing to 3,000 psi for 30-mins.good test. PU Weatherford's Lateral Assembly #1, scribe and surface test, good test, MU bit. TIH, tagged DV tool @ 5,008'. Drill DV Tool @ 5,008'. RU Man Welding tester & test 7" casing to 3,000 psi for 30-mins after drilling DV Tool, good test.

01/29/2014 ? Drilled 6-1/8" hole to a depth of 16,482' (7,585? TVD). Ran 199 jts 4-1/2",11.6#, HCP-110, BTC and Baker Frac system. Shoe @ 16,445? and TOL @ 7,631?. Drop 1.25" composite ball and land with 181 bbls pumped with full returns. Ball landed with 600 psi. Pressured up to 2,200 psi, held for 10 minutes to set Baker liner hanger, bled pressure to 500-psi, slacked off 60 klbs, to verify liner hanger was set. PU 60 klbs and test liner hanger packer & 7" casing to 1500 psi for 10 minutes, good test. Pressured up to 3200 psi on drill pipe and held 3 min released running tool from liner and set open hole packers. Bled pressure down to 500 psi and stung out of liner. Pressure bled off to 0 psi verifying we were free from liner. Shoe set @ 16,437' with TOL @ 7,623'.

01/30/2014 ? Install wellhead cap and release McVay #5 @ 6:00 AM CST 1/31/2014.