

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company COG Operating LLC	Contact Pat Ellis
Address 550 W. Texas, Suite 1300 Midland, Texas 79701	Telephone No. (432) 230-0077
Facility Name Willow "A" State	Facility Type Tank Battery

Surface Owner: State	Mineral Owner	Lease No. (API#) 30-015-33012
----------------------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter J	Section 3	Township 25S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32 09.454 Longitude 104 04.456

NATURE OF RELEASE

Type of Release: Oil	Volume of Release 24 bbls	Volume Recovered 23 bbls
Source of Release: Circulating pump	Date and Hour of Occurrence 1/31/2011	Date and Hour of Discovery 1/31/2011 5:00a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour 3/15/10 4:59 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

¼" nipple on circulating pump started leaking when the pump was turned on, due to worn out threads. The nipple and valves have been replaced and the circulating pump has been put back into service.

Describe Area Affected and Cleanup Action Taken.*

The spill footprint remained inside the facilities firewall; Tetra Tech inspected the site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. The site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez		Approved by District Supervisor: 	
Title: Project Manager		Approval Date: 4/21/11	Expiration Date: NA
E-mail Address: Ike.Tavarez@TetraTech.com		Conditions of Approval:	
Date: 12/14/11	Phone: (432) 682-4559	Final	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2 RP-603