

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

n Hamp 1411832156

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 260737

Contact: Tony Savoie

Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220

Telephone No. 575-887-7329

Facility Name: PLU-411 Tank Battery

Facility Type: Exploration and Production

Surface Owner: Federal

Mineral Owner: Federal

API No. 30-015-39930

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	28	24S	31E	1000	North	1850	East	Eddy

Latitude N 32.193096 Longitude W 103.780815

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 10 Bbls.	Volume Recovered: None
Source of Release: Facility flare	Date and Hour of Occurrence: 4/8/14 at 6:30 p.m.	Date and Hour of Discovery: 4/8/14 at 6:30 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Was reported to the BLM upon discovery due to acreage involved	
By Whom? Tony Savoie	Date and Hour: 4/9/14 8:00 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A valve was discovered closed going to the scrubber on the facility flare line. The vessels pressured up sending crude oil out the flare line. The valves were restored to normal operations.

Describe Area Affected and Cleanup Action Taken.*

The spill impacted and area approximately 1300 ft. X 300 ft. with a fine mist that covered the vegetation and the surface of the soil with less than 1/8" of saturation. The spill also misted just the vegetation in an area approximately 1800 ft. X 400 ft. The vegetation in the immediate area around the flare line was washed down with a soap and micro-blaze mixture on 4/9/14. The site was reviewed again on 4/23/14; there was no residue visible on the soil surface and only light to no residue visible on the vegetation, there was no dead vegetation observed. A series of soil samples will be collected from the surface of the impacted area to determine any further remediation required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: [Signature]	
Title: Waste Management and Remediation Specialist	Approval Date: 4/28/14	Expiration Date: NA
E-mail Address: tasavoie@basspet.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: 4/24/14	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

5/28/14

2RP-22600