<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
811 S. First St., Artesia, NM 88210
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Revised August 8, 2011 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action											
							OR			l Repo	
							Contact: Tony Savoie BOPCO. Clay Gordy Aquila Telephone No. BOPCO 575-887-7329, Aquila 940-761-3153				
Facility Name:		04 Carist	Jau, IN.IVI. 00220	Facility Type: Drilling Rig							
Surface Owner	nl		Mineral O								
LOCATION OF RELEASE											
Unit Letter   Se	Township	Range	Feet from the		South Line	Feet from the	East/West Line	County	<del></del>		
					Nor	th	1926	East	Eddy		
Latitude N 32.381464 Longitude W 103.883210											
NATURE OF RELEASE											
Type of Release:	Stornes 1" ho	Ca		Volume of Release: 1000 gallons Volume Recovered: 400 gallons  Date and Hour of Occurrence: Date and Hour of Discovery:							
Source of Release: Bulk Storage 1" hose						1/13/14 approximately 5:00 a.m. 1/13/14 at approximately 5:00 a.m.					
Was Immediate Notice Given?  ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? Mike Bratcher NMOCD, Jim Amos BLM, John Wells NMED					
By Whom? Tony Savoie						Date and Hour: NMOCD 1/13/14 at 10:33 a.m., BLM at 10:57a.m., NMED at 11:00 a.m.					
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Vo	lume Impacting the	he Watercourse.	RECEIVED	7	
If a Watercourse	acted, Descri	be Fully.*	•				APR 2 9 2014	1			
MOCD ARTESIA											
Describe Cause of Problem and Remedial Action Taken.* Fuel was being transferred via a 1" hose, the hose was laid on the ground un-attended and the valve was left open. The valve was closed upon discovery.											
Describe Area Affected and Cleanup Action Taken.*  The spill impacted and area approximately 50 ft. X 50 ft. around the diesel storage tanks and approximately 185 ft. of containment ditch that had been dug around the tanks and generators. Approximately 400 gallons of diesel was recovered, remediation will take place after the rig, tanks and generators have been removed. The rig moved off location on 4/20/14. DFSI, will begin remediation activities on 4/29/14. The waste generated by the spill will be tested to determine the complete waste characteristics before moving off-site  The spill area will be cleaned up in accordance to the NMOCD, BLM and NMED remediation guidelines.											
regulations all ope public health or the should their opera	erators an he enviro ations hav nt. In add	re required to nment. The a ve failed to ad dition, NMO	report and acceptance lequately in acceptance.	d/or file certain rel c of a C-141 report investigate and rer	ease not by the l nediate	ifications and NMOCD man contamination	d perform correct rked as "Final Re n that pose a threa the operator of re	ive actions for rele port" does not reli at to ground water esponsibility for co	uant to NMOCD rules and asses which may endanger eve the operator of liability surface water, human her ompliance with any other	У	
	- <del>-</del> -	~		OIL CONSERVATION DIVISION							
Signature: 1	<u> </u>	ua									
Printed Name: Tony Savoie Printed Name: Clay Gordy Operations Mgr. for Aquila						Approved by Environmental Specialist:					
Title: Waste Management and Remediation Specialist Ap						Approval Date: 5/2/14 Expiration Date: NA					
E-mail Address: ta			200 y 420 556 973	Re		per OCD Rule & (		Attached			
Date: <del>4/24/14</del> <b> </b>	s If Necessar	ry Pł	none: 432-556-873	like		BLM. <u>SUBMIT I</u> SAL NO LATER T Ce/2/C/		ZRP-2285	<u>_</u>		