


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

### Release Notification and Corrective Action

nHmp 1414850392


Name of Company: Mewbourne Oil Company 14744		OPERATOR	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Address: PO Box 5270 Hobbs NM 88241		Contact: Zack Thomas	
Facility Name: Long Draw 10 E Federal #1		Telephone No. 575-393-5905	
		Facility Type: Producing Oil-Well	
Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-36879	

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	10	20S	25E	2310'	North	990'	West	Eddy

Latitude 32.588808 Longitude -104.478037

### NATURE OF RELEASE

Type of Release: Oil(9 bbls)	Volume of Release: 9 bbls	Volume Recovered: 8 bbls
Source of Release: Oil Well	Date and Hour of Occurrence 5-13-14	Date and Hour of Discovery 5-13-14 9:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Ricky Apperson	Date and Hour 3-27-14 9:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*  High flow rate of oil coming in and failure to close thief hatch on oil tank allowed oil to be released into secondary containment.		
Describe Area Affected and Cleanup Action Taken.*  Affected area- Inside the containment. Cleanup- Vacuum truck came and sucked up standing fluid from inside the containment (a total of 8 bbls were recovered and taken to Tweedy SWD). pressure washer cleaned of tanks and catwalk. Containment was lined with poly therefore no dig and haul was necessary.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature:	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist: 	
Title: Environmental Rep.	Approval Date: 5/28/14	Expiration Date: NA
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b> 6/25/14	
Date: 5-15-14 Phone: 575-602-2188	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2PP-2311