


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

Submit a Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP1415740123 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	PYOTE WATER SOLUTIONS, LLC	Contact	JERRY BURTON
Address	400 W ILLINOIS, STE 950 Midland Tx 79701	Telephone No.	432-448-4917
Facility Name	FANNING SWD 294873	Facility Type	DISPOSAL
Surface Owner	Pyote	Mineral Owner	Pyote
		API No.	30-015-20920

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	4	195	26E	SOUTH	SOUTH	1980	WEST	Eddy

Latitude 32.68763 Longitude 104.3889

NATURE OF RELEASE


Type of Release	rainwater flowed of location w/ salt	Volume of Release	unknown	Volume Recovered	0
Source of Release	Rainstorm	Date and Hour of Occurrence	5/23 to 5/25	Date and Hour of Discovery	5-23 to 5-25
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* On Friday May 23, 2014 Eddy county got hit with a heavy rainstorm with flash floods, golf ball size hail. Our county was in the flash flood warning and heavy rainfall affect until Sunday May 25, 2014.

Describe Area Affected and Cleanup Action Taken.\* Pyote Water Solutions had a crew out on May 28, 2014. Removed rain water, used Vac truck to suck out rain water out of containment, on which we hauled off location. Used backhoe and brought in dump truck to replace chalice and rock. Rebuilding containment around it and starting reclamation as well.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Jerry Burton		Approved by Environmental Specialist: 	
Title: New Mexico Superintendent for Pyote Water Solutions, llc		Approval Date: 6/6/14	Expiration Date: NA
E-mail Address: jerry@pyotewatersystems.com		Conditions of Approval:	
Date: 6-2-14 Phone: 432-448-4917		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule &  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL NO LATER THAN:

7/6/14

2RP-2330