Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103 October 25, 2005
District DECEIVED Energy, Minerals and Natural Resources	
1625 1: Frence Dr., Hobbs, NM, 88240 District II 9 9 2014 HOBBS OCOL CONSERVATION DIVISION	30-015-01533
1301 W. Grandlave., Artesia, NM 88210	5. Indicate Type of Lease
Disrtict III 1000 Rie Braces Roll Aztec, NM 87410 MAY 2 2 2014 District IV Santa Fe, NM 87505	STATE 🗹 FEE 🗌
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505 RECEIVED	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO	7. Lease Name or Unit Agreement Name
A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUC	
PROPOSALS.) 1. Type of Well: Oil Well 🗹 Gas Well 🗌 Other	8. Well Number 41
2. Name of Operator	9. OGRID Number
Apache Corporation 3. Address of Operator	873 10. Pool Name
303 Veterans Airpark Ln., Ste. 3000, Midland, TX, 79705	Empire Abo
4. Well Location Unit Letter M : 990 feet from the S line and	330 feet from the W line
Section 25 Township 17S Range 28E	NMPM County Eddy
11. Elevation (Show whether DR, RKB,RT, GR, etc.) 3656' GR	
12. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A 212 2-11-13	
PULL OR ALTER CASING	
DOWNHOLE COMMINGLE	al Valley Elect. Coop. has ed to remore power lines.
OTHER: 🗌 🔽 Location i	is ready for OCD inspection after P&A
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. 	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from the lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
 All other environmental concrens have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from 	
non-retrieved flow lines and pipelines.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one	
inspection has to be made to a P&A location because it does not meet the criteria above, a penalt	y may be assessed.
SIGNATURE TITLE P&A Ter	chDATE5/16/14
TYPE OR PRINT NAME Leon Sellers leon.sellers@apac	checorp.com PHONE: 432-208-0349
For State Use Only	
APPROVED BY: Jory Marshall TITLE Compliance	Strices DATE 6/10/14
Conditions of Approval (if any):	