

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No. 575-887-7329	
Facility Name: Golden "D" Federal #4 ZRP-2218	Facility Type: Exploration and Production	
Surface Owner Federal	Mineral Owner Federal	API No. 30-015-35636


LOCATION OF RELEASE

Unit Letter I	Section 17	Township 21S	Range 29E	Feet from the 2310	North/South Line South	Feet from 330	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------	------------------------	-------------

Latitude 32.478527 Longitude -103.999193

NATURE OF RELEASES

Type of Release: Produced water/oil	Volume of Release 10 bbls/1bbl	Volume Recovered 1/0
Source of Release: Connection on casing choke	Date and Hour of Occurrence 3/6/14 time unknown	Date and Hour of Discovery: 3/6/14 9:30 A.M.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Brian Wall	Date and Hour: 09/06/2013	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* NA		



Describe Cause of Problem and Remedial Action Taken.*
The casing choke developed a leak. The well was shut in, closed all valves and bled down pressure with a vacuum truck.

Describe Area Affected and Cleanup Action Taken.* ☐ The release impacted approximately 4300 sq. ft. of well pad area. Based on conditions observed at the time of the site assessment and review of aerial photos, this spill is nearly directly on top of a previous spill at the well location All of the free standing fluid was recovered. DFSI was retained, and the site remediated in accordance with BLM and NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Tony Savoie</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: Tony Savoie	Approval Date: <i>6/5/14</i>	Expiration Date: <i>NA</i>
Title: Waste Management and Remediation Specialist	Conditions of Approval: <i>Final</i>	
E-mail Address: tasovie@basspet.com	Attached <input type="checkbox"/>	
Date: <i>05/15/14</i> <i>5/30/14</i> Phone: 432-556-8730		

* Attach Additional Sheets If Necessary