


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

Release Notification and Corrective Action

*nHMP/417639885*

Name of Company <i>Oxy Permian Ltd.</i>		Contact <i>Chancey Summers</i>	
Address <i>1017 W. Stanolind Rd, Hobbs, NM 88240</i>		Telephone No. <i>(575) 397-8216</i>	
Facility Name <i>Riverbend B Federal #8 SWD Battery</i>		Facility Type <i>Battery</i>	
Surface Owner <i>BLM</i>		Mineral Owner	
		API No. <i>30-015-28390</i> (nearest well)	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	23	24S	29E					Eddy County, NM

Latitude N 32.20871° Longitude W 103.96273°

NATURE OF RELEASE

Type of Release <i>Produced water</i>	Volume of Release <i>240 bbls</i>	Volume Recovered <i>230 bbls</i>
Source of Release <i>Fatigue on a 4" poly line from the well to the battery</i>	Date and Hour of Occurrence <i>06/03/2014</i>	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Mike Bratcher, NMOCD and Jennifer VanCuren, BLM</i>	
By Whom? <i>Kathy Purvis, BBC International</i>	Date and Hour <i>06/04/2014 @ 9:40 am</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Fatigue on a 4" poly line from the well to the battery caused 240 bbls of produced water to leak onto the ground. A vacuum truck recovered 230 bbls of produced water and the line was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is 20' x 50' inside the containment area. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: <i>Chancey Summers</i>		Approved by Environmental Specialist:	
Title: <i>HES Specialist</i>		Approval Date: <i>6/25/14</i>	Expiration Date: <i>NA</i>
E-mail Address: <i>Chancey.Summers@oxy.com</i>		Conditions of Approval:	
Date: <i>6-23-14</i>	Phone: <i>(575) 397-8216</i>	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>7/25/14</i>	
		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

*28P-2358*