


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Release Notification and Corrective Action

n HMP1417549415

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: Linn Operating 269 324		Contact: Brian Wall	
Address: 2130 W. Bender Hobbs, NM 88240		Telephone No.: 575-738-1739	
Facility Name: Skelly A Battery (Skelly 226)		Facility Type: Battery	
Surface Owner: Federal		Mineral Owner:	
		API No.: (Closest well) 3001529182	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	22	17S	31E	1217	North	1117	East	Eddy

Latitude: 32.8240028210473 Longitude: -103.852583004542

NATURE OF RELEASE

Type of Release: Produced Water / Oil	Volume of Release: 110 bbls / 110 bbls	Volume Recovered: 60 bbls / 90 bbls
Source of Release: 3" polyline	Date and Hour of Occurrence: 06/03/2014	Date and Hour of Discovery: 06/03/2014 0830
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jennifer Van Curen- BLM Mike Bratcher-NM OCD	
By Whom? Brian Wall	Date and Hour 06/10/2014 1030	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: 3 inch poly line leading off of Free water knock out to water tank broke due to age/corrosion. Entire vessel emptied and new production continued to empty onto ground for the amount of time it took me to shut in the field (approx 1 hour)...upon arrival of the vac truck we began clean up immediately.		
Describe Area Affected and Cleanup Action Taken.* : Area affected approximately 60' long x 3' wide, then went down into a ditch approximately 30' long x 3' wide.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature:	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by District Supervisor:	
Title: Construction Foreman II	Approval Date: 6/24/14	Expiration Date: NA
E-mail Address: bwall@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06/11/2014	Phone: 806-367-0645	

* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines, &
like approval by BLM. SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:

7/24/14

2RP-2352