

Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

Energy, Minerals and Natural Resources

Revised July 18, 2013

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-015-34745
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 648-74
7. Lease Name or Unit Agreement Name Senita State
8. Well Number 1
9. OGRID Number 24010
10. Pool name or Wildcat Undesignated Millman Morrow, South

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>
2. Name of Operator V-F PETROLEUM INC.
3. Address of Operator P.O. BOX 1889, MIDLAND, TEXAS 79702
4. Well Location Unit Letter <u>E</u> : <u>1,540</u> feet from the <u>North</u> line and <u>1070</u> feet from the <u>WEST</u> line Section 4 Township 19-S Range 28-E NMPM Eddy County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,553' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐  
OTHER: TEMPORARILY ABANDON ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6/27/2014 - Pressure Test Annulus between 5 1/2" and 9 5/8" casing to 500# for 30 minutes. There was no pressure loss.


Temporary Restricted Status Approved  
Until 8/7/2017  
LAST PROD 6/1/2013

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE



TITLE Engineering Technician

DATE 07/10/2014


Type or print name Eric Sprinkle

E-mail address: eric@vfpetroleum.com

PHONE: 432-683-3344

For State Use Only


APPROVED BY:



TITLE COMPLIANCE OFFICER

DATE 7/15/14

Conditions of Approval (if any):



Graphic Controls

V-F P1K2

Oxy Sensitive

6-27-14

Pressure Pumping

DATE 6-27-14

BR 222

TH 1235

520

525

PRINTED IN U.S.A.