



District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nMLB/4/9/27797 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: Chevron 4323	Contact: Brian Criswell
Address: 1616 West Bender	Telephone No.: (575) 263 - 0409
Facility Name: Culebra Bluff SWD #1	Facility Type: Injection Station

Surface Owner: State	Mineral Owner:	API: 30-015-22754
----------------------	----------------	-------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E:	2	23S	28E					Eddy

Latitude: N 32° 20' 10.98" Longitude: W 104° 3' 48.82"
32-336540 104.063190

NATURE OF RELEASE

Type of Release: produced water	Volume of Release: 58 bbls	Volume Recovered: 53 bbls
Source of Release: injection station	Date and Hour of Occurrence: 6/14/14 @ am	Date and Hour of Discovery: 6/14/14 @ am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Brian Criswell	Date and Hour: 6/14/14 @ am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
Depth to Water: ~25 ft bgs		
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* Approximately 58 bbls of produced water were released when the pump equipment failed at the battery releasing 58 barrels of produced water to the secondary containment; no produced water escaped the containment. A vacuum truck was dispatched to pick up any free standing liquids. There were approximately 53 bbls recovered. An Emergency Response Team arrived at the release area and began continuous abatement of the impacted area. Visibly stained soil was excavated and hauled away for disposal at a state approved facility.		
Describe Area Affected and Cleanup Action Taken.* Approximately 2,300 square feet of surface area was impacted by the release. Soil samples will not be collected from release area due to finding a poly liner while removing contaminated soil. All contaminated soil will be removed and hauled for disposal. Upon NMOCD approval, EPI will backfill the tank battery.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature:	OIL CONSERVATION DIVISION	
Printed Name: Brian Criswell	Approved by District Supervisor:	
Title: HSE Specialist	Approval Date: 7/10/14	Expiration Date: N/A
E-mail Address: brian.criswell@chevron.com	Conditions of Approval: Verify Liner Integrity upon repair of casing material	Attached <input type="checkbox"/>
Date:	Phone: (575) 263-0409	

* Attach Additional Sheets If Necessary

2RP-2368

Bratcher, Mike, EMNRD

From: Daniel Dominguez <ddominguezepi@gmail.com>
Sent: Monday, July 07, 2014 11:01 AM
To: Bratcher, Mike, EMNRD; Criswell, Brian
Subject: Culebra Bluff SWD #1 Initial C-141
Attachments: Culebra Bluff SWD #1 Initial C-141.pdf

Mr. Bratcher,

Attached in PDF is the signed Initial C-141 for the Culebra Bluff SWD #1 operated by Chevron.

--

Sincerely,
ENVIRONMENTAL PLUS, INC.

Daniel Dominguez
Environmental Consultant/Safety Director

Environmental Plus, Inc.
P.O. Box 1558
2100 Avenue 'O'
Eunice, NM 88231
(575) 631-0401 (Cell)
(575) 394-3481 (Office)
(575) 394-2601 (fax)