

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP1419929757

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 260737	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: James Ranch Unit 31	Facility Type: Exploration and Production

Surface Owner: State of N.M.	Mineral Owner: State of N.M.	API No. 30-015-30829
------------------------------	------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	36	22S	30E	1980	North	1980	East	Eddy

Latitude N 32.350402 Longitude W 103.832032

NATURE OF RELEASE



Type of Release: Crude oil and Produced water	Volume of Release: 1 bbl oil and 4 bbls PW	Volume Recovered: 1 bbl total fluid
Source of Release: 1/4" Hose	Date and Hour of Occurrence: 6/16/14 time unknown	Date and Hour of Discovery: 6/16/14 at approximately 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*	NM OIL CONSERVATION ARTESIA DISTRICT JUL 10 2014
---	---

Describe Cause of Problem and Remedial Action Taken.* A 1/4" hose going from the wellhead to a high pressure kill switch ruptured. The hose has been replaced.	RECEIVED
---	-----------------

Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 750 sq.ft. of caliche pad. A vacuum truck removed the free-standing fluid, the stained soil was left in place until the area can be cleaned up in accordance to the NMOCD remediation rules.
--

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: 	
Title: Waste Management and Remediation Specialist	Approval Date: 7/18/14	Expiration Date: NA
E-mail Address: tasavoie@basspet.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: 7/10/14	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

8/18/14

2RP-2370