								REC	EN/E	D		
District II Energy Mineral 1301 W. Grand Avenue, Artesia, NM 88210 Oil Cons 1000 Rio Brazos Road, Aztec, NM 87410 1220 South						of New Mexico Is and Natural Resources ervation Division th St. Francis Dr. Fe, NM 87505 AUG 2 2/2014 NMOCD ARTESIA Short 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form						
			Rele	ease Notific			orrective	Action	1			
Name of Company OGRID Number						ATOR Initial Report Final Report Contact						
Name of CompanyOGKID NumberYates Petroleum Corporation25575						Robert Asher						
Address 104 S. 4 TH Street						Telephone No. 575-748-1471						
Facility Name API Number						Facility Type						
Bebop BPE	State Con	1 #1-H		30-015-3755	1	Battery						
Surface OwnerMineral OwnerStateState						r Lease No VO-7679					:	
LOCATION OF RELEASE												
Unit Letter D			Feet from the 660'	1	/South Line North	Feet from th 330'		East/West Line West		County Eddy		
Latitude_32.09213 Longitude_103.73863												
NATURE OF RELEASE												
Type of Release Produced Water						Volume of Release Volume Re 1750 B/PW 1700 B/PW						
Source of Release						Date and Hour of Occurrence Date and H				Hour o	lour of Discovery	
Produced water flow line Was Immediate Notice Given?						5/13/2014; 12:30 PM 5/13/2014; 12:30 PM If YES, To Whom? 5/13/2014; 12:30 PM						
Yes No Not Required										Ţ	RECEIVED	
By Whom? Robert Asher/Yates Petroleum Corporation						Date and Hour 5/14/2014, AM (Email)					AUG 2 2 2014	
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse. N/A						
If a Watercourse was Impacted, Describe Fully.* N/A										N	MOCD ARTERIA	
Describe Cause of Problem and Remedial Action Taken.*												
The water flow line ruptured from pressure build-up, causing the release. Vacuum truck(s) were called, roustabout crew called to repair line. Describe Area Affected and Cleanup Action Taken.*												
An approximate area of 50' X 125' (north side of production pad) and an approximate area of 100' X 150' (west side of production pad). Flow line repaired. Production pad will be scraped; impacted soils will be taken to an NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's a Final Report, C- 141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL a work plan will be submitted to the OCD. Depth to Ground Water: >100' (approximately 325', per the ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 0.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
Signature: CJAQU .						OIL CONSERVATION DIVISION Signed By Mills Brances						
Printed Name: Robert Asher						Approved by District Supervisor:						
Title: NM Environmental Regulatory Supervisor						Approval Date: 3/25/14 Expiration D				Date:	N/A	
E-mail Addre	ss: boba@y		Conditions of Approval:				Atta	ched				
Date: Thursd			Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION									
Attach Addi	tional Shee	_	PROPOSAL NO LATER THAN: 2RP-2454 9125114									