

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

OCT 03 2013

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report

X Final Report

Name of Company	BOPCO, LP	Contact	Tony Savoie
Address	522 W. Mermod, Suite 704, Carlsbad, NM 88220	Telephone No.	(432)556-8730
Facility Name	Bass 3 Federal Well #4 Spill Site "B"	Facility Type	E&P

Surface Owner	Federal	Mineral Owner	Federal	Lease No.	
---------------	---------	---------------	---------	-----------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	3	22S	28E					Eddy

Latitude 32.417420° North

Longitude 104.072281° West

NATURE OF RELEASE

Type of Release	Produced water and crude oil	Volume of Release	45 bbls of produced water and 5 bbls of crude oil	Volume Recovered	None
Source of Release	3" poly flow line	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	12/13/11 11:46 a.m.
Was Immediate Notice Given?	X Yes No Not Required	If YES, To Whom?	Mike Bratcher NMOCD and Jim Amos BLM		
By Whom?	Tony Savoie	Date and Hour	12/13/11 12:12 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* The flow line delivering produced fluid from the well to the tank battery developed a leak. The well was shut in, and a temporary pipe clamp was placed on the affected area. The entire flow line was replaced with poly pipe prior to remediation activities.

Describe Area Affected and Cleanup Action Taken.\* The released fluid affected an area of approximately 5000 sq. ft. of pasture land. Following initial response activities, both releases were remediated as per NMOCD recommended guidelines. Please reference the attached *Remediation Summary & Risk-Based Site Closure Request* for remediation details.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>		OIL CONSERVATION DIVISION	
Printed Name: <u>Tony Savoie</u>		Approved by District Supervisor: <u>[Signature]</u>	
Title:		Approval Date: <u>9/4/14</u>	Expiration Date: <u>NA</u>
E-mail Address:		Conditions of Approval: <u>Final</u>	
Date: <u>10/31/13</u>	Phone:		

2 RP-98/