

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Lost Tank 35 State 4 CTB	Facility Type	Battery

Surface Owner	Oxy	Mineral Owner		Lease No.	V-3604
---------------	-----	---------------	--	-----------	--------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	35	21S	31E					Eddy County, NM

Latitude N 32.42818° Longitude W 103.75586°

NATURE OF RELEASE

Type of Release	Oil & Produced water	Volume of Release	5 bbls oil & 20 bbls produced water	Volume Recovered	0 bbls
Source of Release	Transfer line leak	Date and Hour of Occurrence	5/30/12	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- OCD		
By Whom?	Chancey Summers	Date and Hour	6/4/12 @ 3:35 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A transfer line leak caused 5 bbls of oil and 20 bbls of produced water to spill onto the ground. No fluids were recovered. Remediation will be performed according to an OCD approved remediation plan.

Describe Area Affected and Cleanup Action Taken.*

The area affected is approximately 60' x 200'. A transfer line leak caused 5 bbls of oil and 20 bbls of produced water to spill onto the ground. No fluids were recovered. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 01/13/2014/

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				OIL CONSERVATION DIVISION			
Printed Name:	Chancey Summers			Approved by District Supervisor: 			
Title:	HES Specialist			Approval Date:	8/13/14	Expiration Date:	NA
E-mail Address:	Chancey_Summers@oxy.com			Conditions of Approval:		Attached <input type="checkbox"/>	
Date:	5-19-14			Phone:		(575) 397-8216	

* Attach Additional Sheets If Necessary

22P-1609