

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

OCT 02 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1427548938

OPERATOR

☒ Initial Report ☐ Final Report

| | |
|---|----------------------------|
| Name of Company: COG Operating LLC | Contact: Robert McNeill |
| Address: 600 West Illinois Avenue, Midland TX 79701 | Telephone No. 432-230-0077 |
| Facility Name: McIntyre B #7 | Facility Type: Well |

| | | |
|------------------------|------------------------|----------------------|
| Surface Owner: Federal | Mineral Owner: Federal | API No. 30-015-31561 |
|------------------------|------------------------|----------------------|

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| M | 20 | 17S | 30E | 660' | South | 660' | West | Eddy |

Latitude 32.8137724103499 Longitude -104.001670530599

NATURE OF RELEASE

| | | |
|--|---|--|
| Type of Release: Oil and Produced Water | Volume of Release: 5 bbls Oil ; 10 bbls PW | Volume Recovered: 3 bbls Oil ; 8 bbls PW |
| Source of Release: Flowline | Date and Hour of Occurrence: 9/15/2014 1:00 pm | Date and Hour of Discovery: 9/15/2014 1:00 pm |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | |
| By Whom? | Date and Hour: | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The release was caused by corroded flowline. Repairs were made to the line and a vacuum truck was dispatched to pick up all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

The impacted area occurred at the NE corner of the location and ran into the pasture. The area was treated with microblaze. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Amanda Trujillo

Printed Name: Amanda Trujillo

Approved by Environmental Specialist:

Heber

Title: Senior Environmental Coordinator

Approval Date: 10/2/14

Expiration Date:

NA

E-mail Address: atrujillo@concho.com

Conditions of Approval:

Attached ☐

Date: October 2, 2014

Phone: 575-748-6940

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 11/2/14

* Attach Additional Sheets If Necessary

2RP-2519