

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

OCT 08 2014
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

Name of Company: BOPCO, L.P. <i>2100737</i>		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Contact: Tony Savoie		
Facility Name: PLU-CVX-JV #005H (AKA Big Sinks 25 Federal #1H)		Telephone No. 575-887-7329		
		Facility Type: Exploration and Production		
Surface Owner: Federal		Mineral Owner: Federal	API No. 30-015-39018	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	25	24S	30E	100	South	2240	East	Eddy

Latitude N 32.18193 Longitude W 103.83318

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 10 bbls of crude oil and 109 bbls produced water.	Volume Recovered: 5 bbls crude oil and 75 bbls produced water.
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence: 10/1/14 time unknown	Date and Hour of Discovery: 10/1/14 at approximately 10:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104	
By Whom? Bradley Blevins	Date and Hour: 10/1/14 at approximately 4:30 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The buried flow line developed a leak due to external corrosion. A repair clamp was placed on the leak area. Crews replaced the flow line across the well pad with externally coated pipe on 10/2/14.		
Describe Area Affected and Cleanup Action Taken.* The release impacted approximately 9,656 sq.ft. of caliche well pad area. All of the free standing fluid was removed with a vacuum truck. The stained area on the pad was left as is pending remediation activities. The spill area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Signed By: <i>M. L. Brannon</i>	
Title: Waste Management and Remediation Specialist		Approved by Environmental Specialist:	
E-mail Address: tasavoie@basspet.com		Approval Date: 10/18/14	Expiration Date: N/A
Date: 10/17/14 Phone: 432-556-8730		Conditions of Approval:	
Remediation per O.C.D. Rules & Guidelines		Attached <input type="checkbox"/>	
SUBMIT REMEDIATION PROPOSAL NO			
LATER THAN: 11/5/14		2RP-2526	

* Attach Additional Sheets If Necessary