

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

OCT 10 2014

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1428733041

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	RKI E&P, LLC	Contact	Zack Laird
Address	210 Park Ave. - Ste. 900, OKC, OK 73102	Telephone No.	405-742-2696
Facility Name	Federal G Gas Com #1	Facility Type	Oil and Gas Well

Surface Owner	Federal	Mineral Owner	Federal	API No.	30-015-20848
---------------	---------	---------------	---------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	21	20S	30E		1650 FSL		1900FEL	Eddy

Latitude 32.5561146081723 Longitude -103.974812991781

NATURE OF RELEASE

Type of Release. Oil and Produced Water	Volume of Release 15Bbls	Volume Recovered 14Bbls
Source of Release Produced Water Tank	Date and Hour of Occurrence 10/09/14 - Unknown	Date and Hour of Discovery 10/09/14 - 0900hrs
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* N/A



Describe Cause of Problem and Remedial Action Taken.*

Produced Water tank developed a hole and allowed PW to leak from tank into secondary containment (earthen). A vacuum truck was used to recover free liquids and empty tank.

Describe Area Affected and Cleanup Action Taken.*

All fluid remained in earthen tank dike, free fluids were recovered with vacuum truck.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Zack Laird	Approved by Environmental Specialist: 	
Title: Sr. EHS Manager	Approval Date: 10/10/14	Expiration Date: NA
E-mail Address: ZLaird@rkixp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/09/14	Phone: 405-987-2213	

* Attach Additional Sheets If Necessary

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 11/10/14

2RP-2542