

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

OCT 13 2014

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1428742057		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company: COG Operating LLC		Contact: Robert McNeill			
Address: 600 West Illinois Avenue, Midland TX 79701		Telephone No. 432-230-0077			
Facility Name: McIntyre DK #15		Facility Type: Battery			
Surface Owner: Federal		Mineral Owner: Federal		API No. 30-015-40896	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	17	17S	30E	261'	South	2618'	West	Eddy

Latitude 32.8280730541828 Longitude -103.994208840473

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 30 bbls Oil ; 60 bbls PW	Volume Recovered: 29 bbls Oil ; 59 bbls PW
Source of Release: Gasket Failure	Date and Hour of Occurrence: 10-10-2014 5:30 am	Date and Hour of Discovery: 10-10-2014 5:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD / Jim Amos - BLM	
By Whom? Amanda Trujillo	Date and Hour: 10-13-2014 9:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



A gasket failure on a heater treater caused the release. This release occurred within a lined facility, however an overspray of 20' x 40' impacted the pasture to the south. No standing pools formed as a result of the spray. Vacuum trucks were dispatched to pick up all standing fluid in berm and dispose of at an NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.*

Once all standing fluid was retrieved an pressure washer cleaned equipment and removed gravel. The pasture was treated with soapy water on vegetation and Microblaze on the soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist 	
Printed Name: Amanda Trujillo		
Title: Senior Environmental Coordinator	Approval Date:	Expiration Date:
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: October 13, 2014 Phone: 575-748-6940		

LIKE APPROVAL BY

BLM

2BP2548

* Attach Additional Sheets If Necessary