

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

OCT 23 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1429655452

OPERATOR

X Initial Report ☐ Final Report

Name of Company: Burnett Oil Co., Inc. - 3080	Contact Leslie Garvis
Address 801 Cherry Street-Suite 1500, Ft. Worth, TX 76102	Telephone No. 817-583-8730
Facility Name: Jackson A 31 H	Facility Type: Well

Surface Owner: BLM	Mineral Owner BLM	API No. 30-015-34000
--------------------	-------------------	----------------------

LOCATION OF RELEASE

Unit Letter B	Section 24	Township 17S	Range 30E	Feet from the 1220	North/South Line FNL	Feet from the 2310	East/West Line FEL	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude: _____ Longitude: _____

NATURE OF RELEASE

Type of Release: Crude Oil & Produced Water	Volume of Release: 15/40	Volume Recovered: 0/0
Source of Release: Well head	Date and Hour of Occurrence: 10/22/14	Date and Hour of Discovery: 10/22/14
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM - Jeff Robertson	
By Whom? Eddie Duran	Date and Hour: 10/22/14	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Flow line at the well head became plugged and ruptured.

Describe Area Affected and Cleanup Action Taken.*
Spill was on pad and ran into pasture area, no product was recovered. Area will be delineated and remediated according to NM regulations. Approx. 150'x10' in pasture & pooled in 20'x30' area, small area on pad.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Leslie Garvis</i>	OIL CONSERVATION DIVISION	
Printed Name: Leslie M. Garvis	Approved by Environmental Specialist:	
Title: Regulatory Coordinator	Approval Date: 10/23/14	Expiration Date: N/A
E-mail Address: lgarvis@burnettoil.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/23/14 Phone: 817-583-8730	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 11/23/14	

* Attach Additional Sheets If Necessary

2RP-2563